



Name: **MacDonough House (N-424)**

Location: **McDonough, Delaware**

Photographer: **Staff, B/A&HP**

Date: **1978**

Location of Negative: **Div. of Historical & Cultural Affairs,  
B/A&HP, Hall of Records, Dover, Delaware 19901**

Description: **Facade from east**

Photograph Number: **1**

**JUN 30 1978**

**DEC 12 1978**



Name: **MacDonough House (N-424)**

Location: **McDonough, Delaware**

Photographer: **Staff, B/A&HP**

Date: **1978**

Location of Negative: **Div. of Historical & Cultural Affairs,  
B/A&HP, Hall of Records, Dover, Delaware 19901**

Description: **North end wall showing raised roof**

Photograph Number: **2**

**JUN 30 1978**

**DEC 12 1978**



Name: **MacDonough House (N-424)**

Location: **McDonough, Delaware**

Photographer: **Staff, B/A&HP**

Date: **1978**

Location of Negative: **Div. of Historical & Cultural Affairs,  
B/A&HP, Hall of Records, Dover, Delaware 19901**

Description: **Rear of House from west showing additions**

Photograph Number: **3**

JUN 30 1978

DEC 12 1978



Name: **MacDonough House (N-424)**

Location: **McDonough, Delaware**

Photographer: **Staff, B/A&HP**

Date: **1978**

Location of Negative: **Div. of Historical & Cultural Affairs,  
B/A&HP, Hall of Records, Dover, Delaware 19901**

Description: **Rear facade, brick portion. Note belt course,  
water table and segmentally arched windows.**

Photograph Number: **4**

**JUN 30 1978**

**DEC 12 1978**





Name: **MacDonough House (N-424)**

Location: **McDonough, Delaware**

Photographer: **Staff, B/A&HP**

Date: **1978**

Location of Negative: **Div. of Historical & Cultural Affairs,  
B/A&HP, Hall of Records, Dover, Delaware 19901**

Description: **Interior view of the north room on the  
second floor in the brick section showing the central  
field of the panelled end wall.**

Photograph Number: **5**

JUN 30 1978

DEC 12 1978



Name: **MacDonough House (N-424)**

Location: **McDonough, Delaware**

Photographer: **Staff, B/A&HP**

Date: **1978**

Location of Negative: **Div. of Historical & Cultural Affairs,  
B/A&HP, Hall of Records, Dover, Delaware 19901**

Description: **Interior view (etc. as above) showing the  
right field of the panelled end wall.**

Photograph Number:       **6**

**JUN 30 1978**

**DEC 12 1978**



Name: **MacDonough House (N-424)**

Location: **McDonough, Delaware**

Photographer: **Staff, B/A&HP**

Date: **1978**

Location of Negative: **Div. of Historical & Cultural Affairs,  
B/A&HP, Hall of Records, Dover, Delaware 19901**

Description: **Detail of cupboard over fireplace with  
butterfly shelves.**

Photograph Number: **7**

**JUN 30 1978**

**DEC 12 1978**



Name: MacDonough House (N-424)

Location: McDonough, Delaware

Photographer: Staff of B/A&HP

Date: 1978

Location of Negative: Div. of Historical & Cultural Affairs,  
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: Detail of window skirt in north room, first  
floor of brick section.

Photograph Number: 8

JUN 30 1978

DEC 12 1978





Name: **MacDonough House (N-424)**

Location: **McDonough, Delaware**

Photographer: **Staff, B/A&HP**

Date: **1978**

Location of Negative: **Div. of Historical & Cultural Affairs,  
B/A&HP, Hall of Records, Dover, Delaware 19901**

Description: **Detail of mantel in north room on first floor  
of brick section.**

Photograph Number: **9**

JUN 30 1978

DEC 12 1978



Name: **MacDonough House (N-424)**

Location: **McDonough, Delaware**

Photographer: **B/A&HP**

Date: **1978**


Location of Negative: **Div. of Historical & Cultural Affairs,  
B/A&HP, Hall of Records, Dover, Delaware 19901**

Description: **Detail of mantel in first floor room, frame  
section.**

Photograph Number: **10**

**JUN 30 1978**

**JUN 12 1978**



Name: **MacDonough House (N-424)**

Location: **McDonough, Delaware**

Photographer: **Staff, B/A&HP**

Date: **1978**

Location of Negative: **Div. of Historical & Cultural Affairs,  
B/A&HP, Hall of Records, Dover, Delaware 19901**

Description: **South side of outbuildings behind MacDonough  
House**

Photograph Number:

**11**

**JUN 30 1978**

**DEC 12 1978**



Name: **MacDonough House (N-424)**

Location: **McDonough, Delaware**

Photographer: **Staff, B/A&HP**

Date: **1978**

Location of Negative: **Div. of Historical & Cultural Affairs,  
B/A&HP, Hall of Records, Dover, Delaware 19901**

Description: **West end of Root Cellar**

Photograph Number: **12**

**JUN 30 1978**

grapher:

ion of Neg

**DEC 12 1978**





3



1



4



2



5

Commodore Thomas MacDonough House

Location: McDonough, New Castle Co., Delaware

Photographer: Staff, B/AHP

Date: November, 1978

Location of Negative: Division of Historical & Cultural Affairs, Hall of Records, Dover.

Description: Outbuildings behind MacDonough House as described below and numbered on sketch map.

Photograph Numbers:

1. Looking west from farm lane at barns and pole shed, from left #8,7,6,5 as shown on sketch map.
2. Looking west at barns #13 and 12.
3. Looking east at root cellar (#3), at right is barn (#13).
4. Looking east down lane between barns, to left barn (#6) and animal shed (#5) and in foreground root cellar and shed (#2,3).
5. Looking west down farm lane between barns.

DEC 7 1978

DEC 12 1978