

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES

PROPERTY PHOTOGRAPH FORM

boarding.

Z

R

SEE


SCOTT

FOR NPS USE ONLY

ENTRY NUMBER 1 1 197 ATE

	(Type all	entries - attach to or enclose	with photograph)	ENTRY NUMBER 1 1 1973 ATE		
1.	NAME			. 1		
-	соммон:	Osburn House	MELLIND			
	AND/OR HISTORIC:	Osburn House	1	(2)		
2.	LOCATION		The state of the s	59 50		
Janes .	STREET AND NUMBE		19 1972	123		
	U.S. 25 about 1/4 mile south of Burton Pike intersection					
	CITY OR TOWN:	-	ON NATIONAL	The same and		
	Ge	eorgetown	PEGISTER	LEPA /		
	STATE:	C	CODE COUNTY:		CODE	
		Kentucky	21	Scott	209	
3.	PHOTO REFERENC	E	4 19V			
	PHOTO CREDIT: Ann Bevins					
	DATE OF PHOTO: 1971					
	Route # 4-Lexington Pike, Georgetown, Ky. 40324					
4	IDENTIFICATION					
-	DESCRIBE VIEW,	DIRECTION, ETC.				
	Showing the house, which faces east, taken from				ıeast	

prior to the restoration which involved stripping of weather-



	NATIONAL PARK SERVICE	<u>Kentucky</u>				
	NATIONAL REGISTER OF HISTORIC PLACES	COUNTY Scott				
	PROPERTY PHOTOGRAPH FORM	FOR NPS USE ONLY				
S	(Type all entries - attach to or enclose with photograph)	ENTRY NUMBER DATE				
	(Type an entires attach to of enclose with photograph)	APR 1 1 1973				
Z	1. NAME					
0	common: Osburn House					
_	and/or historic: Osburn House	31/12//				
\vdash	2. LOCATION					
U	STREET U.S. 25 about 1/4 mile south of Burton Pike intersection					
2	Georgetown	DEC 19 1972 (a)				
S	Kentucky Code County:	REGISCOTT CODE 209				
Z	3. PHOTO REFERENCE	11/2 LOV				
-	PHOTO CREDIT: Ann B. Bevins	11911				
	DATE OF PHOTO: 1979					
Ш	Route # 4-Lexington Pike, Georgetown, Ky. 40324					
S	4. IDENTIFICATION					
	DESCRIBE VIEW, DIRECTION, ETC.					
	Showing the facade after weatherboarding was stripped as part of a restoration taking place during 1972. Taken from the northeast.					

UNITED STATES DEPARTMENT OF THE INTERIOR

STATE

