

United States Department of the Interior
National Park Service

National Register of Historic Places Continuation Sheet

Section number _____ Page _____


SUPPLEMENTARY LISTING RECORD

NRIS Reference Number: 91001784 **Date Listed:** 12/20/91

Brash, Anna C., House **Jackson** **MISSISSIPPI**
Property Name **County** **State**

Historic Resources of Pascagoula, MS
Multiple Name

This property is listed in the National Register of Historic Places in accordance with the attached nomination documentation subject to the following exceptions, exclusions, or amendments, notwithstanding the National Park Service certification included in the nomination documentation.

for 
Signature of the Keeper

7/10/92
Date of Action

=====
Amended Items in Nomination:

Section No. 10

This nomination was amended to show the acreage as less than 1 acre.

This change was confirmed by phone with the Mississippi SHPO (1/9/92).

DISTRIBUTION:
National Register property file
Nominating Authority (without nomination attachment)

1759

United States Department of the Interior National Park Service

National Register of Historic Places Registration Form

This form is for use in nominating or requesting determinations of eligibility for individual properties or districts. See instructions in Guidelines for Completing National Register Forms (National Register Bulletin 16). Complete each item by marking "x" in the appropriate box or by entering the requested information. If an item does not apply to the property being documented, enter "N/A" for "not applicable." For functions, styles, materials, and areas of significance, enter only the categories and subcategories listed in the instructions. For additional space use continuation sheets (Form 10-900a). Type all entries.

1. Name of Property

historic name Brash, Anna C. House
other names/site number Hines, Paul W., Jr. House

2. Location

street & number 802 Buena Vista Street N/A not for publication
city, town Pascagoula N/A vicinity
state Mississippi code MS county Jackson code 59 zip code 39567

3. Classification

Ownership of Property: [x] private, [] public-local, [] public-State, [] public-Federal
Category of Property: [x] building(s), [] district, [] site, [] structure, [] object
Number of Resources within Property: Contributing (1), Noncontributing (2 buildings, sites, structures, objects), Total (2)

Name of related multiple property listing: Historic Resources of Pascagoula, MS
Number of contributing resources previously listed in the National Register: 0

4. State/Federal Agency Certification

As the designated authority under the National Historic Preservation Act of 1966, as amended, I hereby certify that this [x] nomination [] request for determination of eligibility meets the documentation standards for registering properties in the National Register of Historic Places and meets the procedural and professional requirements set forth in 36 CFR Part 60. In my opinion, the property [x] meets [] does not meet the National Register criteria. [] See continuation sheet.
Signature of certifying official: Kenneth H. P. Paul
Date: Oct. 24, 1991
Deputy State Historic Preservation Officer
State or Federal agency and bureau

In my opinion, the property [] meets [] does not meet the National Register criteria. [] See continuation sheet.
Signature of commenting or other official
Date
State or Federal agency and bureau

5. National Park Service Certification

I, hereby, certify that this property is:
[] entered in the National Register. [] See continuation sheet.
[] determined eligible for the National Register. [] See continuation sheet.
[] determined not eligible for the National Register.
[] removed from the National Register.
[] other, (explain:)
Signature of the Keeper: [Signature]
Date of Action: 12-20-91

6. Function or Use

Historic Functions (enter categories from instructions)

Domestic/Single Dwelling

Current Functions (enter categories from instructions)

Domestic/Single Dwelling

7. Description

Architectural Classification
(enter categories from instructions)

Stick/Eastlake

Materials (enter categories from instructions)

foundation Brick

walls Weatherboard

roof Asphalt

other N/A

Describe present and historic physical appearance.

The Anna Brash house faces west on a flat lot facing Buena Vista street. Set at the southwest corner of the lot, there is a generous north side yard, and east back yard with two outbuildings in the northeast corner. There are some small trees and foundation planting, but the landscaping is not of note.

The house is a simple gable-ended structure running east and west, with a rather highly developed front facade. The house is clad with weatherboards and corner boards above a water table and bottom fascia. It sits about three feet or more above grade on brick piers, the spaces between the piers covered with open-work brick on the front porch.

The simply pitching roof is penetrated by a nicely corbelled-top brick chimney on the outside wall towards the center of the south side. The roof projects out moderately at the side eaves. The fascia on the side walls under the eaves continues out to become the front fascia of the porch soffit beam, and the boxing of the eaves runs horizontally across the front of the gable. The verges of the gable repeat the thin, moderately projecting eaves, and the front surface of the gable has a fascia at the verges, and is weatherboarded. A later pair of one-over-one double-hung sash separated by mullions are centered on the gable. Below is a later thin balcony of turned spindles, its floor below the sill level of the sash.

The three-bay porch is supported by square section posts with a high length at the bottom supporting a railing of turned balusters, a length at the top with delicate jigsaw brackets resembling butterfly wings, and with three equal square-sectioned elements the rest of the shaft, these sections separated from each other and the top and bottom square lengths by recessed turnings.

Access to the wood floored porch is up steps, with no handrail, at the north end of the porch, leading directly to the front door, which is a large framed opening with a single-acting door with a top glass pane and lower decorative wood panel, the door set below a two-light transom. Next to a mullion each side of the door bay are three-light side-light sash with wood panels below the full height of the frame. To the south are two full-length two-over-four double-hung sash with louvered blinds. All three openings have a small molding capping the top of the trim, the door opening frame being a little higher than the window frames.

On the south side there are, going east, spaced irregularly, five typical two-over-two window sash, the center opening being two sash with a muntin set in one frame. None have blinds.

**United States Department of the Interior
National Park Service**

**National Register of Historic Places
Continuation Sheet**

Section number 7 Page 2

The Brash house is a side-hall cottage. The hall is on the north side of the house, and has an L-shaped stair with turned wood newel post, turned wood banisters, and open stringer. The wall separating the hall from the street-facing living room has been removed. The living room is backed by a bathroom, then a bedroom. Across the rear, backing up to the hall and bedroom, is the den, which was originally the kitchen. The present kitchen was added during the 1920s. The typical interior door has five panels, no transom, and a casing comprised of a flat board with molded backband. The base is elaborately detailed, but the cornice is fairly restrained. Walls and ceilings are of wood boards, but covered with Celetex.

In the northeast corner of the lot is a non-contributing wood frame grage with gable roof, wood siding, and sliding garage doors. There are no visible windows. South of the garage is a small, non-contributing, prefabricated fiberglass greenhouse.


United States Department of the Interior
National Park Service

National Register of Historic Places Continuation Sheet

Section number 7 Page 3



802 BUENA VISTA



8. Statement of Significance

Certifying official has considered the significance of this property in relation to other properties:

nationally statewide locally

Applicable National Register Criteria A B C D

Criteria Considerations (Exceptions) N/A A B C D E F G

Areas of Significance (enter categories from instructions)

Architecture

Period of Significance

1900

Significant Dates

1900

Cultural Affiliation

N/A

Significant Person

N/A

Architect/Builder

unknown

State significance of property, and justify criteria, criteria considerations, and areas and periods of significance noted above.

802 Buena Vista is architecturally significant within the context of Pascagoula's residential elements, as one of only a few surviving historic side-hall cottages in the city. It is also significant as the home of Anna C. Brash, widow of the lighthouse keeper of Horn Island, relating it to the area's maritime context.

A previous house on this site, built in 1889 by Hans Grandahl, was destroyed by fire. Before her marriage, Mrs. Brash acquired the property in 1900 from W.O. Clark, manager of J.H. Menge & Sons, and erected the present house. She later married Brash, who was keeper of the Horn Island lighthouse, which began operation on May 23, 1874. The house stayed in the Brash family until 1960 when it was sold to Doris Stringer. Other owners include Alfred A. Frank, 1965; David Hanafourda, 1977; Michael J. Heidelberg, 1978, and Paul W. Hines, 1981.

The house dates from the period when East Pascagoula was a separate community, noted for its resort industry and port activity. The house is one of only a few surviving shotguns in Pascagoula, a house type which once was prolific in the community (see cover nomination). The porch details are particularly well executed, and were made possible because of the area's lumber industry.

9. Major Bibliographical References

For bibliography see context statement.

N/A See continuation sheet

Previous documentation on file (NPS):

- preliminary determination of individual listing (36 CFR 67) has been requested
- previously listed in the National Register
- previously determined eligible by the National Register
- designated a National Historic Landmark
- recorded by Historic American Buildings Survey # _____
- recorded by Historic American Engineering Record # _____

Primary location of additional data:

- State historic preservation office
- Other State agency
- Federal agency
- Local government
- University
- Other

Specify repository: _____

10. Geographical Data

Acreage of property _____

UTM References

A
 Zone Easting Northing

C

B
 Zone Easting Northing

D

See continuation sheet

Verbal Boundary Description

Pt. Lot 41 E/S Buena Vista Street, Eugenia Baptiste TR S/D
SEC 8-8-6, DB 630-413 DB 663-B DB 710-556 418M866.16

N/A See continuation sheet

Boundary Justification

The boundary includes the entire city lot that has historically been associated with the property.

N/A See continuation sheet

11. Form Prepared By

name/title Robert J. Cangelosi, Jr., Architect

organization Koch and Wilson Architects, A Prof. Corp. date 3 June 1991

street & number 1100 Jackson Avenue telephone 504/581-7023

city or town New Orleans state LA zip code 70130