


1366



The Frank G. Edwards House
San Francisco, California
Gerald B. Levine
January, 1982
1366 Guerrero Street

View of brick retaining wall and wire
and cast iron fence with gate taken
at close range in a northwesterly
direction.

Photograph Number 1 of 12.



The Frank G. Edwards House
San Francisco, California
Gerald B. Levine
January, 1982
1366 Guerrero Street

View of the west side of the 1300 block
of Guerrero Street showing 1366 Guerrero
as part of the streetscape, and taken
from the southeast looking north and
west.

Photograph Number 2 of 12.



The Frank G. Edwards House
San Francisco, California
Gerald B. Levine
January, 1982
1366 Guerrero Street

Slightly-angled full view including landscaping, retaining wall, and wire and cast iron fencing with gate. Taken from the east side of Guerrero somewhat south of the property looking west.

Photograph Number 3 of 12.



The Frank G. Edwards House
San Francisco, California
Gerald B. Levine
January, 1982
1366 Guerrero Street

Mid-range full view of house including landscaping, retain wall, wire and caste iron fence and gate. Taken from the middle of Guerrero Street looking west and slightly north.

Photograph Number 4 of 12 .



The Frank G. Edwards House
San Francisco, California
Gerald B. Levine
January, 1982
1366 Guerrero Street

Close-range view of facade emphasizing
fenestration and portico detailing.
Taken from the southeast toward
the northwest.

Photograph Number 5 of 12.



The Frank G. Edwards House
San Francisco, California
Gerald B. Levine
January, 1982
1366 Guerrero Street

Detail photograph emphasizing entrance
portico and including window ornament.
Taken at close range on a north-
westerly angle.

Photograph Number 6 of 12.



The Frank G. Edwards House
San Francisco, California
Gerald B. Levine
January, 1982
1366 Guerrero Street

Detail of entryway and front door
taken at close range and looking
almost due west.

Photograph Number 7 of 12 .



The Frank G. Edwards House
San Francisco, California
Gerald B. Levine
January, 1982
1366 Guerrero Street

Detail of interior stair and newell
post taken from southeast corner
of entrance hall toward the north-
west.

Photograph Number 8 of 12.



The Frank G. Edwards House
San Francisco, California
Gerald B. Levine
January, 1982
1366 Guerrero Street

View of the west wall of the parlor
with north wall to the right.
Doorway left rear to dining room.
Shows ceiling medallion and light
fixture, and overall effect of wall
and ceiling papers as well as mouldings.


Photograph Number 9 of 12.



The Frank G. Edwards House
San Francisco, California
Gerald B. Levine
January, 1982
1366 Guerrero Street

Detail photograph of parlor fireplace
which is on south wall of the house.


Photograph Number 10 of 12 .



The Frank G. Edwards House
San Francisco, California
Gerald B. Levine
January, 1982
1366 Guerrero Street

Detail of northwest corner of parlor
ceiling emphasizing relationships
between wall and ceiling papers,
mouldings and cornices.

Photograph Number 11 of 12 .



The Frank G. Edwards House
San Francisco, California
Gerald B. Levine
January, 1982
1366 Guerrero Street

Detail of painted and gilded ceiling
medallion centered in the parlor
ceiling and showing a portion of
the light fixture.

Photograph Number 12 of 12.