

Photographer: James R. Lockhart
Negative filed: Georgia Department
of Natural Resources
Date: November, 1983
Description (1 of 13): Front facade;
photographer facing west.



Photographer: James R. Lockhart Negative filed: Georgia Department of Natural Resources Date: November, 1983 Description ( 2 of 13): South facade; photographer facing northwest.



Photographer: James R. Lockhart
Negative filed: Georgia Department
of Natural Resources
Date: November, 1983

of Natural Resources
Date: November, 1983
Description (3 of 13): North facade; photographer facing southwest.



Photographer: James R. Lockhart Negative filed: Georgia Department of Natural Resources Date: November, 1983 Description (4 of 13): Rear view, showing parsonage; photographer facing northeast.



Photographer: James R. Lockhart
Negative filed: Georgia Department
of Natural Resources
Date: November, 1983
Description (5 of 13): Detail, northwest
corner, showing church (left) and par-

southeast.

sonage (right); photographer facing



Photographer: James R. Lockhart Negative filed: Georgia Department of Natural Resources Date: November, 1983 Description (6 of 13): Sanctuary, looking toward altar; photographer facing west.



Photographer: James R. Lockhart Negative filed: Georgia Department of Natural Resources Date: November, 1983 Description (7 of 13): Altar; photographer facing northwest.



Photographer: James R. Lockhart Negative filed: Georgia Department of Natural Resources Date: November, 1983 Description (8 of 13): Sanctuary, looking toward vestibule; photographer facing northeast.



Photographer: James R. Lockhart Negative filed: Georgia Department of Natural Resources Date: November, 1983 Description (9 of 13): Sanctuary, looking toward altar from balcony; photographer facing west.



Photographer: James R. Lockhart

Negative filed: Georgia Department of Natural Resources Date: November, 1983 Description (10 of 13): "General Conference" stained-glass window of east facade, from balcony; photographer facing southeast.



Photographer: James R. Lockhart Negative filed: Georgia Department of Natural Resources Date: November, 1983 Description (11 of 13): North stairwell in vestibule; photographer facing north.



Photographer: James R. Lockhart Negative filed: Georgia Department of Natural Resources Date: November, 1983

Description (12 of 13): South stairwell in vestibule (being prepared for elevator); photographer facing south.



Photographer: James R. Lockhart Negative filed: Georgia Department of Natural Resources Date: November, 1983 Description (13 of 13): Ground floor, under renovation; photographer facing west.