







The James Armor House (N-506)

4905 Lancaster Pike

Wilmington, Christiana Hundred, Delaware 19807

Valerie Cesna

February, 1990

State of Delaware

Bureau of Archaeology and Historic Preservation

15 The Green

Dover, DE 19901

Side of House Showing Facade of Early Nineteenth  
Century Section

Camera Facing West.

20F11



The James Armor House (N-506)

4905 Lancaster Pike

Wilmington, Christiana Hundred, Delaware 19807

Valerie Cesna

February, 1990

State of Delaware

Bureau of Archaeology and Historic Preservation

15 The Green

Dover, DE 19901

3/4 Side and Facade of House Showing Early  
Twentieth Section and Mid-Nineteenth Century Section  
Camera Facing Northeast.

3 of 11









The James Armor House (N-506)

4905 Lancaster Pike

Wilmington, Christiana Hundred, Delaware 19807

Anne Wilson

February, 1990

State of Delaware

Bureau of Archaeology and Historic Preservation

15 The Green

Dover, DE 19901

East End Wall of Parlor. Camera Facing East.

5 of 11



The James Armor House (N-506)

4905 Lancaster Pike

Wilmington, Christiana Hundred, Delaware 19807

Anne Wilson

February, 1990

State of Delaware

Bureau of Archaeology and Historic Preservation

15 The Green

Dover, DE 19901

End wall of Front Parlor. Camera Facing West

6 of 11



The James Armor House (N-596)

4905 Lancaster Pike

Wilmington, Christina Hundred, Delaware 19701

Valerie Cesna

February, 1990

Bureau of Archaeology and Historic Preservation

15 The Green

Dover, DE 19901

North Endwall of Early Nineteenth Century Section

Camera Facing North

TOP 11



The James Armor House (N-506)

4905 Lancaster Pike

Wilmington, Christiana Hundred, Delaware 19807

Valerie Cesna

February, 1990

State of Delaware

Bureau of Archaeology and Historic Preservation

15 The Green

Dover, DE 19901

Detail of Window Reveal in Early Eighteenth Section

First Floor. Camera Facing Northeast.

8 of 11





The James Armor House (N-506)

4905 Lancaster Pike

Wilmington, Christiana Hundred, Delaware 19807

Valerie Cesna

February, 1990

Bureau of Archaeology and Historic Preservation


15 The Green

Dover, DE 19901

Supplementary Bracing For Added Portion Attic Endwall  
in Early Nineteenth Century Section of House

Camera Facing Southeast

9 of 11



The James Armor House (N-506)

4905 Lancaster Pike

Wilmington, Christiana Hundred, Delaware 19807

Valerie Cesna

February, 1990

State of Delaware

Bureau of Archaeology and Historic Preservation

15 The Green

Dover, DE 19901

View to Well-House in Basement of Early Eighteenth  
Century Section Camera Pointing West

100F 11



The James Armor House (N-506)

4905 Lancaster Pike

Wilmington, Christiana Hundred, Delaware 19807

Valerie Cesna

February, 1990

State of Delaware

Bureau of Archaeology and Historic Preservation

15 The Green

Dover, DE 19901

Facade of Garage. Camera Facing West.

11 of 11