



PHOTOGRAPH 1

Commodore Hull School, Shelton, Ct.  
Arnold Goodman October 1981 photo  
Neg. on file CT Historical Commission  
Facade and north side, looking south-  
west on Oak Avenue.



PHOTOGRAPH 2

Commodore Hull School, Shelton, Ct.

Arnold Goodman October 1981 photo

Neg. on file Ct. Historical Commission  
(East) Facade, looking west from Oak  
Avenue.



PHOTOGRAPH 3

Commodore Hull School, Shelton, Ct.

William E. Devlin July, 1982 photo

Neg. on file Ct. Historical Commission

Front (east) entrance, looking west  
from Oak Avenut.





PHOTOGRAPH 4

Commodore Hull School, Shelton, Ct.

William E. Devlin July, 1982 photo

Neg. on file Ct. Historical Commission

South side, looking south; Note side

entrance





STANDARD  
PREMISES  
SUPERVISOR  
CITY  
ENGINEER  
THE WALL  
ST. LOUIS

PHOTOGRAPH 5

Commodore Hull School, Shelton, Ct.

William E. Devlin July, 1982 photo

Neg. on file Ct. Historical Commission

North side, looking west



PHOTOGRAPH 6

Commodore Hull School, Shelton, Ct.

William E. Devlin July, 1982 photo

Neg. on file Ct. Historical Commission

Rear on west side, looking east.



PHOTOGRAPH 7

Commodore Hull School, Shelton, Ct.  
Arnold Goodman October 1981 photo  
Neg. on file Ct. Hist. Commission  
Interior first floor classroom





PHOTOGRAPH 8

Commodore Hull School, Shelton, Ct.  
William E. Devlin July, 1982 Photo  
Neg. on file Ct. Historical Commission  
Interior of 1st floor, looking south  
Note floor beams, concrete, exposed  
terra cotta block.



PHOTOGRAPH 9

Commodore Hull School, Shelton, Ct.

William E. Devlin July, 1982 photo

Neg. on file Ct. Historical Commission

Vestibule of front (east) entrance,

looking east. Note tile walls, transom.