England Farm, Topeka, KS.
Photo credit: NP Small
Neg. on file: K.S.H.S
View of north (front) facade

1874

England Farm, Topeka, KS.
Photo credit: NP Small
Neg. on file: K.S.H.S.
View of east facade

Note datestone.

2 of 21

England Farm, Topeka, KS.
Photo credit: NP Small
Neg. on file: KS.S. H.S.
View from southeast

England Farm, Topeka, KS.
Photo credit: NP Small
Neg. on file: K.S.H.S.
View from southwest

England Farm, Topeka, KS.
Photo credit: NP Small
Neg. on file: K.S.H.S.
View from east of old ice-house and of farmhouse

England Farm, Topeka, KS.
Photo credit: NP Small
Neg. on file: K.S.H.S.
View from southeast
Note windmill and granary

England Farm, Topeka, KS.
Photo credit: NP Small
Neg. on file: K.S.H.S.
View of outbuildings to south of house.

England Farm, Topeka, KS.
Photo credit: NP Small
Neg. on file: K.S.H.S.
View of outbuildings to south of house.

England Farm, Topeka, KS.
Photo credit: NP Small
Neg. on file: K.S.H.S.
View of yard to south of house

England Farm, Topeka, KS.
Photo credit: NP Small
Neg. on file: K.S.H.S.
View of granary from the west

England Farm, Topeka, KS.
Photo credit: NP Small
Neg. on file: K.S.H.S.
View of granary from northeast

England Farm, Topeka, KS.
photo credit: NP Small
Neg. on file: K.S.H.S.
Icehouse from the southeast

England Farm, Topeka, KS.
Photo credit: NP Small
Neg. on file: K.S.H.S.
View toward barns from house

England Farm, Topeka, KS.
Photo credit: NP Small
Neg. on file: K.S.H.S.
View of barn from northeast

England Farm, Topeka, KS.
photo credit: NP Small
Neg. on file: K.S.H.S.
Detail of north entrance of barn

England Farm, Topeka, KS.
Photo credit: NP Small
Neg. on file: K.S.H.S.
View of west facade of barn

England Farm, Topeka, KS.
Photo credit: NP Small
Neg. on file: K.S.H.S.
View from southwest of c. 1910 barn addition

England Farm, Topeka, KS.
Photo credit: NP Small
Neg. on file: K.S.H.S.
View of barn complex from East

England Farm, Topeka, KS.
Photo credit: NP Small
Neg. on file: K.S.H.S.
View of barn complex from southeast



England Farm, Topeka, KS.
Photo credit: NP Small
Neg. on file: K.S.H.S.
Ground level of c. 1910 barn.

England Farm, Topeka, KS.
photo credit: NP Small
Neg. on file: K.S.H.S.
View of pegged construction in c. 1874
barn