



Sheriff Mill Complex

Pickens County, S.C.

Hurley Badders, Feb. 11, 1987

Pendleton District Historical

& Recreational Commission

Pendleton, S.C.

East elevation of Main House



Sheriff Mill Complex

Pickens County, S.C.

Hurley Badders, Feb. 11, 1987

Pendleton District Historical
& Recreational Commission

Pendleton, S.C.

East (right) and south (left)
elevations of Main House



Sheriff Mill Complex

Pickens County, S.C.

Hurley Badders, Feb. 11, 1987

Pendleton District Historical
& Recreational Commission

Pendleton, S.C.

North (left) and west (right)
elevations of Main House



Sheriff Mill Complex

Pickens County, S.C.

Hurley Badders, Feb. 11, 1987

Pendleton District Historical
& Recreational Commission

Pendleton, S.C.

South elevation, Main House



Sheriff Mill Complex
Pickens County, S.C.
Hurley Badders, Feb. 11, 1987
Pendleton District Historical
& Recreational Commission
Pendleton, S.C.
West elevation, Main House



Sheriff Mill Complex

Pickens County, S.C.

Hurley Badders, Feb. 11, 1987

Pendleton District Historical
& Recreational Commission

Pendleton, S.C.

North elevation, Main House



Sheriff Mill Complex

Pickens County, S.C.

Hurley Badders, Feb. 11, 1987

Pendleton District Historical
& Recreational Commission

Pendleton, S.C.

Detail, Main House: shingle

work on front gable



Sheriff Mill Complex

Pickens County, S.C.

Hurley Badders, Feb. 11, 1987

Pendleton District Historical
& Recreational Commission

Pendleton, S.C.

Main House: front entrance



Sheriff Mill Complex

Pickens County, S.C.

Hurley Badders, Feb. 11, 1987

Pendleton District Historical
& Recreational Commission

Pendleton, S.C.

Mantel in second floor bedroom

Main House



Sheriff Mill Complex

Pickens County, S.C.


Hurley Badders, March 24, 1987

Pendleton District Historical

& Recreational Commission

Pendleton, S.C.

Main House: mantel in living
room, downstairs



Sheriff Mill Complex

Pickens County, S.C.

Hurley Badders, March 24, 1987

Pendleton District Historical
& Recreational Commission

Pendleton, S.C.

Interior of Main House: detail
of door framing, upstairs bedroom



Sheriff Mill Complex

Pickens County, S.C.

Hurley Badders, March 24, 1987

Pendleton District Historical
& Recreational Commission

Pendleton, S.C.

Interior, Main House

stairway in front hall



Sheriff Mill Complex

Pickens County, S.C.

Hurley Badders, March 24, 1987

Pendleton District Historical
& Recreational Commission

Pendleton, S.C.

Southwest elevation of Miller's Residence showing addition



Sheriff Mill Complex

Pickens County, S.C.

Hurley Badders, March 24, 1987

Pendleton District Historical
& Recreational Commission

Pendleton, S.C.

Southwest elevation of

Miller's Residence



Sheriff Mill Complex

Pickens County, S.C.

Hurley Badders, March 24, 1987

Pendleton District Historical
& Recreational Commission

Pendleton, S.C.

East elevation Sheriff Gristmill



Sheriff Mill Complex
Pickens County, S.C.
Hurley Badders, March 24, 1987
Pendleton District Historical
& Recreational Commission
Pendleton, S.C.
Sheriff Gristmill: Southeast
view showing water wheel



Sheriff Mill Complex
Pickens County, S.C.
Hurley Badders, Feb. 11, 1987
Pendleton District Historical
& Recreational Commission
Pendleton, S.C.

Northwest view of Sheriff Gristmill 1



Sheriff Mill Complex

Pickens County, S.C.

Hurley Badders, March 24, 1987

Pendleton District Historical

& Recreational Commission

Pendleton, S.C.

East elevation Sheriff Gristmill



Sheriff Mill Complex

Pickens County, S.C.

Hurley Badders, Feb. 11, 1987

Pendleton District Historical
& Recreational Commission

Pendleton, S.C.

South elevation, Sheriff Gristmill



Sheriff Mill Complex

Pickens County, S.C.

Hurley Badders, Feb. 11, 1987

Pendleton District Historical &

Recreational Commission

Pendleton, S.C.

Dam and Millpond



Sheriff Mill Complex

Pickens County, S.C.

Hurley Badders, March 24, 1987

Pendleton District Historical
& Recreational Commission

Pendleton, S.C.

View of the Mill Pond and Main
House from the Northeast