



East Providence Multiple Resource Area/36/51

Boston and Providence Railroad Bridge
East Providence, R.I.

Photographer: Robert O. Jones
Date: December 1979


NOV 28 1980

OCT 24 1980

Negative filed at: Rhode Island Historical
Preservation Commission
150 Benefit Street
Providence, R.I.

Overall view facing south-southwest, showing
stone abutments of bridge linked by deck truss
spans.

Photo #36.



East Providence Multiple Resource Area/37/51

Boston and Providence Railroad Bridge
East Providence, R.I.

Photographer: Robert O. Jones
Date: December 1979

NOV 28 1980

OCT 24 1980

Negative filed at: Rhode Island Historical
Preservation Commission
150 Benefit Street
Providence, R.I.

View of northeastern abutment of bridge over
Roger Williams Avenue, facing northwest.

Photo #37.