

DEC 29 1978

NOV 18 1977

ALTERATIONS TO INTEGRITY  
COMPARE TO PHOTO 2 OF SAME SECTION

MORO ROCK STAIRWAY IN 1931

SEQUOIA NATIONAL PARK, CA

PHOTO BY <sup>WILLIAM</sup> TWEED, 1977

NEGATIVE FILED AT:

SEQUOIA NAT. PARK


THREE RIVERS, CA

TRAIL BETWEEN SURVEY

POINTS 200 AND 270

(COMPARE TO 1931 VIEW)

PHOTO 1 OF 5



S31D137

DEC 29 1978

NOV 18 1971


MORO ROCK STARWAY  
SEQUOIA NAT. PARK, CA  
PHOTO BY DIEHL, 1931

NEGATIVE FILED AT:

SEQUOIA NAT. PARK  
THREE RIVERS, CA

TRAIL BETWEEN SURVEY  
POINTS 200 AND 270  
(COMPARE TO 1977 VIEW)

PHOTO 2 OF 5



S31D131

DEC 29 1978

NOV 18 1977


MORO ROCK STAIRWAY  
SEQUOIA NAT. PARK, CA  
Photo By DIEHL, 1931

NEGATIVE FILED AT:

SEQUOIA NAT. PARK  
THREE RIVERS, CA

BEGINNING OF 1931  
TRAIL, LOOKING SOUTH  
(COMPARE TO 1977 VIEW)

PHOTO 3 OF 5




SEQUOIA NATIONAL PARK, CA

MORO ROCK STEPS

NPS PHOTO BY <sup>ROBERT</sup> COX, 10/75

PHOTO 4 OF 5





SEQUOIA NATIONAL PARK, CA

MORO ROCK STEPS

ROBERT

NPS PHOTO BY COX, 10/75

PHOTO 5 OF 5