



Webb Block
317 East Main
Bismarck, North Dakota

Photo credit: Sabin Peterson

Date of photo: June 1983

Location of negative: Cultural Research & Management
P.O. Box 2154
Bismarck, North Dakota 58502

Exterior from the northeast

Photo 1 of 12



Webb Block
317 East Main
Bismarck, North Dakota

Photo credit: Sabin Peterson

Date of photo: June 1983

Location of negative: Cultural Research & Management
P.O. Box 2154
Bismarck, North Dakota 58502

Exterior from the northwest

Photo 2 of 12



Webb Block
317 East Main
Bismarck, North Dakota


Photo credit: Sabin Peterson

Date of photo: June 1983

Location of negative: Cultural Research & Management
P.O. Box 2154
Bismarck, North Dakota 58502

Exterior from the south

Photo 3 of 12



VE

Webb Block
317 East Main
Bismarck, North Dakota

Photo credit: Sabin Peterson

Date of photo: June 1983

Location of negative: Cultural Research & Management
P.O. Box 2154
Bismarck, North Dakota 58502

Exterior, detail showing upper portion of an "A" bay
on the north facade.

Photo 4 of 12



Webb Block
317 East Main
Bismarck, North Dakota

Photo credit: Sabin Peterson

Date of photo: June 1983

Location of negative: Cultural Research & Management
P.O. Box 2154
Bismarck, North Dakota 58502

Exterior, detail showing upper portion of the "B" bay
on north facade

Photo 5 of 12



Webb Block
317 East Main
Bismarck, North Dakota


Photo credit: Sabin Peterson

Date of photo: June 1983

Location of negative: Cultural Research & Management
P.O. Box 2154
Bismarck, North Dakota 58502

Interior, main floor original part of the building
from the southwest, on the main stairway

Photo 6 of 12



Webb Block
317 East Main
Bismarck, North Dakota

Photo credit: Sabin Peterson

Date of photo: June 1983

Location of negative: Cultural Research & Management
P.O. Box 2154
Bismarck, North Dakota 58502

Interior, detail showing pressed metal roof on main
floor of building

Photo 7 of 12



Webb Block
317 East Main
Bismarck, North Dakota

Photo credit: Sabin Peterson

Date of photo: June 1983

Location of negative: Cultural Research & Management
P.O. Box 2154
Bismarck, North Dakota 58502

Interior 2nd floor of addition, from the east

Photo 8 of 12



Webb Bros.

Webb Block
317 East Main
Bismarck, North Dakota

Photo credit: Unknown

Date of photo: 1899-1906

Location of negative: State Historical Society of ND
North Dakota Heritage Center
Bismarck, North Dakota 58505

Exterior from the northeast

Photo 9 of 12



Webb Block
317 East Main
Bismarck, North Dakota

Photo credit: Taken from Bismarck, Capitol of North
Dakota, by Mrs. W.F. Cushing, 1916.

Date of photo: 1907-1916

Location of negative: State Historical Society of ND
North Dakota Heritage Center
Bismarck, North Dakota 58505

Exterior from the northwest

Photo 10 of 12



Webb Block
317 East Main
Bismarck, North Dakota

Photo credit: Unknown

Date of photo: 1907-1936

Location of negative: State Historical Society of ND
North Dakota Heritage Center
Bismarck, North Dakota 58505

Exterior from the southeast

Photo 11 of 12



Webb Block
317 East Main
Bismarck, North Dakota

Photo credit: Unknown

Date of photo: September 1955

Location of negative: State Historical Society of ND
North Dakota Heritage Center
Bismarck, North Dakota 58505

Exterior from the Patterson Hotel, from the north east

Photo 12 of 12