



Andreas graf House
Mult. County

VIEW: Northwest corner

1911

Graf (Andreas) House
Corbett vicinity, Multnomah County
Oregon

Photographer unknown, c.1911
Rt 1, Box 1565
Corbett, Oregon 97019

NOV 13 1980

1 of 6
Historic View from the
Northwest, c.1911

FEB 13 1980



Andreas Graf House
Mult. County

VIEW: west side

1911

Graf (Andreas) House
Corbett vicinity, Multnomah County
Oregon

Photographer unknown, c.1911
Rt 1, Box 1565
Corbett, Oregon 97019

NOV 13 1980

2 of 6
Historic view from the
Southwest, c. 1911

FEB 13 1980



Andreas Graf House
Mult. County

View: West Side

11/23/79

Graf (Andreas) House
Corbett vicinity, Multnomah County
Oregon

NOV 13 1980

Juanita Graf photo, 1979
Rt 1, Box 1565
Corbett, Oregon 97019

3 of 6
West (new front) elevation

FEB 13 1980



Andreas Graf House
Mult County

VIEW: South side

11/23/79

Graf (Andreas) House
Corbett vicinity, Multnomah County
Oregon

NOV 13 1980

Juanita Graf photo, 1979
Rt 1, Box 1565
Corbett, Oregon 97019

4 of 6
South elevation

FEB 13 1980



Andreas Graf House
Mult. County

VIEW: EAST Side

11/23/79

Graf (Andreas) House
Corbett vicinity, Multnomah County
Oregon

Juanita Graf photo, 1979
Rt 1, Box 1565
Corbett, Oregon 97019

NOV 13 1980

5 of 6
East elevation

FEB 13 1980



Andreas Graf House
Mult. County

VIEW: North Side

11/23/79

Graf (Andreas) House
Corbett vicinity, Multnomah County
Oregon

Juanita Graf photo, 1979
Rt 1, Box 1565
Corbett, Oregon 97019

NOV 13 1980

6 of 6
North (old front) elevation

FEB 13 1980



Andreas Graf house
ca. 1885

Multnomah County, OREGON
CORBETT VICINITY

VIEW: Northwest

Graf (Andreas) House
Corbett Vicinity
Multnomah County, Oregon NOV 13 1980

Juanita Graff photo, October 1980
Route 1, Box 1565
Corbett, OR 97019 NOV 3 1980

1 of 7

West elevation, showing restoration in progress. Porch roof and uprights rebuilt. Spool work and brackets on porch roof to be reinstalled and replicated

as necessary. Fancy work and acroteria at gable peaks to be replaced.



Andreas Graf house

ca. 1885

Multnomah County, OREGON

CORBETT VICINITY

VIEW: NORTHEAST

Graf (Andreas) House
Corbett Vicinity
Multnomah County, Oregon

NOV 13 1980

Juanita Graff photo, October, 1980
Route 1, Box 1565
Corbett, OR 97019

NOV 3 1980

2 of 7

East elevation, showing porch roof and foundation in process of being restored. Spool work to be reinstalled on porch. Fancy work and acroteria to be replaced

at gable peaks.



Andreas GRAF House

ca. 1885

Multnomah County, OREGON

CORBETT VICINITY

VIEW: BALCONY TRIM, ALSO SAWN WOOD

Graf (Andreas) House

Corbett Vicinity

Multnomah County, Oregon NOV 13 1980

Juanita Graff photo, October, 1980

Route 1, Box 1565

Corbett, OR 97019

NOV 3 1980

3 of 7

Detail of jig-sawn braces North balcony
roof framing system.



ANDREAS Graf House

Ca. 1885

Multnomah County, OREGON

CORBETT VICINITY

VIEW: SOUTHWEST

Graf (Andreas) House
Corbett Vicinity
Multnomah County, Oregon

NOV 13 1980

Juanita Graff photo, October 1980
Route 1, Box 1565
Corbett, OR 97019 NOV 3 1980

4 of 7

West and south elevations, showing
restoration in progress.



ANDREAS GRAF HOUSE

ca. 1885

MULTNOMAH COUNTY, OREGON

CORBETT VICINITY

VIEW: CLOSEUP OF SAWN WOOD TRIM
ON TOWER.

Graf (Adnreas) House
Corbett Vicinity
Multnomah County, Oregon

NOV 13 1980

Juanita Graff photo, October 1980
Route 1, Box 1565
Corbett, OR 97019

NOV 3 1980

5 of 7

Detail of brackets, West tower pyramidal
roof.



Andreas Graf house

ca. 1885

Multnomah County, OREGON

CORBETT VICINITY

VIEW: SOUTH

Graf (Andreas) House
Corbett Vicinity
Multnomah County, Oregon

Juanita Graff photo, October 1980
Route 1, Box 1565
Corbett, OR 97019 NOV 3 1980

6 of 7
South elevation.

NOV 13 1980



Andreas Graf house

ca. 1885

Multnomah County, OREGON

CORBETT, VICINITY

VIEW: SOUTHEAST

Graf (Andreas) House
Corbett Vicinity
Multnomah County, Oregon

NOV 13 1980

Juanita Graff photo, October 1980
Route 1, Box 1565
Corbett, OR 97019

NOV 3 1980

7 of 7

South and East elevations, showing
newly rebuilt chimneys.