



Scott Joplin Residence, 2658-A Morgan St. (now Delmer Blvd.), St. Louis, Mo. J. G. Randall and Associates for ABC



UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

**NATIONAL REGISTER OF HISTORIC PLACES
PROPERTY PHOTOGRAPH FORM**

FOR NPS USE ONLY
RECEIVED
DATE ENTERED

SEE INSTRUCTIONS IN *HOW TO COMPLETE NATIONAL REGISTER FORMS*
TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

1 NAME

HISTORIC

Scott Joplin Residence

AND/OR COMMON

Scott Joplin Residence

2 LOCATION

CITY, TOWN

St. Louis

____ VICINITY OF

STATE

Missouri

COUNTY

St. Louis

3 PHOTO REFERENCE

PHOTO CREDIT

J.G. Randle and Associates

DATE OF PHOTO

3-11-76

NEGATIVE FILED AT

Afro-American Bicentennial Corporation, Washington, D.C.

4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

View from Southeast

PHOTO NO.

1



LOG No Roll #2

Photo No #16

Subject Scott Joplin National
Historic Landmark

Description of View Rear View -
General ENVIRONMENT - to Northwest

Location of Subject 2658 Delmar
Saint Louis, Missouri

Location of Negative National Park
Service, ROCKY MOUNTAIN REGION

By W.P. O'Brien Date 10-22-86



LOG No Roll #2

Photo No #6

Subject Scott Joplin National
Historic Landmark

Description of View Rear View -
ca. 1908 addition and gallery area

Location of Subject 2658 Delmar
Saint Louis, Missouri

Location of Negative National Park
Service, Rocky Mountain Region

By W. P. O'Brien Date 10-22-86



LOG No Roll # 2

Photo No # 7

Subject Scott Joplin National
Historic Landmark

Description of View Rear (South)
Elevation

Location of Subject 2658 Delmar
Saint Louis, Missouri

Location of Negative National Park
Service, Rocky Mountain Region

By W. P. O'Brien Date 10-22-86



LOG No Roll # 4

Photo No # 12

Subject Scott Joplin National
Historic Landmark

Description of View Rear Elevation -
Looking Northeast

Location of Subject 2658 Del Mar
Saint Louis, Missouri

Location of Negative NATIONAL PARK
Service, Rocky Mountain Region

By W. P. O'BRIEN Date 10-22-86



LOG No Roll #4

Photo No #9


Subject Scott Joplin National
Historic Landmark

Description of View Backyard -
General Environment - Bldg. to west

Location of Subject 2658 Delmar
Saint Louis, Missouri

Location of Negative National Park
Service, Rocky Mountain Region

By W. P. O'Brien Date 10-22-86



LOG No Roll # 3

Photo No # 15

Subject Scott Joplin National
Historic Landmark

Description of View Interior - Fire
damage between 1st and 2nd Floors

Location of Subject 2658 Delmar
Saint Louis, Missouri

Location of Negative National Park
Service, Rocky Mountain Region

By W. P. O'Brien Date 10-22-86



LOG No Roll #1
Photo No #7
Subject Scott Joplin National
Historic Landmark
Description of View Typical Interior -
Attic Room
Location of Subject 2658 Delmar
Saint Louis, Missouri
Location of Negative National
Park Service, Rocky Mountain Region
By W.P. O'Brien Date 10-22-86



LOG No Roll #3

Photo No #1

Subject Scott Joplin National
Historic Landmark

Description of View TYPICAL INTERIOR-
SECOND FLOOR

Location of Subject 2658 DeMAR
Saint Louis, Missouri

Location of Negative NATIONAL PARK
SERVICE, ROCKY MOUNTAIN REGION

By W.P. O'Brien Date 10-22-86



LOG No Roll # 3
Photo No # 20
Subject Scott Joplin National
Historic Landmark
Description of View Stairway - 1st
to 2nd floor
Location of Subject 2658 Delmar
Saint Louis, Missouri
Location of Negative National Park
Service, Rocky Mountain Region
By W. P. O'Brien Date 10-22-86



LOG No Roll #3

Photo No #2

Subject Scott Joplin National
Historic Landmark

Description of View Typical INTERIOR -
1st FLOOR

Location of Subject 2658 DELMAR
Saint Louis, Missouri

Location of Negative NATIONAL PARK
SERVICE, ROCKY MOUNTAIN REGION

By W.P. O'BRIEN Date 10-22-86