

Name: Spring Garden

Location: Delaware Ave. Extended, Laurel, Delaware


Photographer: Richard B. Carter

Date: Dec., 1981

Location of Negative: Hall of Records, Dover, DE

Description: Front facade of 18th century brick section.

1 of 13



Names Spring Garden Locations Del. Avenue Extended, Laurel, Delaware Photographers Richard B. Carter Date: Dec., 1981 Location of Negative: Hall of Records, Dover, DE Description: View of east end and rear of original brick section showing water table and double end chimneys. Photograph Numbers 2 of 13




Namen Spring Garden

Location: Delaware Ave. Extended, Laurel, Delaware

Photographer: Richard B. Carter
Date: Dec., 1981
Location of Negative: Hall of Records, Dover, DE

Description: View of shed at rear of house with part of rear of brick section and wood frame rear wing visible in background.

Photograph Number: 3 of 13



Location: Delaware Ave. Extended, Laurel, Delaware

Photographer: Richard B. Carter

Date: Dec., 1981

Name

Location of Negative: Hall of Records, Dover, DE

Description: Detail view showing first floor six-overnine window in original brick section.

Photograph Numbers 4 of 13



Location: Delaware Ave. Extended, Near Laurel, Delaware Photographer: Richard B. Carter

Date: Dec., 1981
Location of Megative: Hall of Records, Dover, DE

Description: View of front and west side of Victorian wing of house. Original brick section is visible at right.

Photograph Numbers 5 of 13

Namen



Name:

Location: Delaware Ave.Extended, Laurel, Delaware

Photographer: Richard B. Carter

Date: Dec., 1981

Location of Negative: Hall of Records, Dover, DE

Description: View of west side and rear of house showing rear frame wing at left and rear and side of later frame wing at right.

Photograph Number: 6 of 13



Name: Spring Garden

Location: Delaware Ave. Extended, Laurel, Delaware

Description: Detail of gable end of front facade

of Victorian wing.

Photograph Numbers 7 of 13

Photographer: Richard B. Carter

Dec., 1981

Date:



Name: Spring Garden

Location: Delaware Ave. Extended, Laurel, Delaware

Photographer: Richard B. Carter Date: Dec., 1980

Description: View of fireplace in second floor "parlor chamber", brick section.

Location of Negative: Hall of Records, Dover, DE

Photograph Number: 8 of 13



Name:

Location: Delaware, Ave. Extended, Laurel, Delaware

Photographer: Richard B. Carter

Date: Dec., 1980

Location of Negative: Hall of Records, Dover, DE

Description: View of fireplace in second floor bedroom, brick section.

Photograph Number: 9 of 13



Location: Delaware Ave. Extended, Laurel, Delaware


Photographer: Richard B. Carter Date: Dec., 1980

Name :

Location of Negative: Hall of Records, Dover, DE

Description: View of east end chimneys in attic showing manner in which they are angled outward.

Photograph Number: 10 of 13



Name: Spring Garden

Location: Delaware Ave. Extended, Laurel, Delaware

Photographer:
Date:

Location of Negative:

Richard B. Carter
Dec., 1980
Hall of Records, Dover, DE

Description: View of interior of attic door in original section showing wooden box lock.

Photograph Numbers 11 of 13



Names

Location: Delaware Ave. Extended, Laurel, Delaware

Photographer: Richard B. Carter
Date: Dec., 1980
Location of Negative: Hall of Records, Dover, DE

Description: View of walnut newel post in Victorian section.

Photograph Number: 12 of 13



Name # Spring Earden
Delaware Ave. Extended, Laurel, Delaware
Location:

Photographer: Richard B. Carter Date: Dec., 1980

Description: Interior view of second floor bedroom in Victorian section.

Location of Negative: Hall of Records, Dover, DE

Photograph Number: 13 of 13