Holmdel Community Church U.C.C. Complex
40 Main St., Holmdel, Monmouth County, N.J.
Photographer: Marilyn Duff
Negatives: Holmdel Community Church
1986

View: from east side of Sanctuary crawl space, looking west at main beam splice

#1 of 24 - spliced main beam and stone pier, probably from the original structure, supporting the Sanctuary floor (mortar applied about 1970)

Holmdel Community Church U.C.C. Complex
40 Main St., Holmdel, Monmouth County, N.J.
Photographer: Edward B. Schumacher

Negatives: from color slide included in nomination

View: from north end of Sanctuary crawl space, looking northeast

#2 of 24 - typical Sanctuary floor joist pier support of unmortared stone probably dating to original church building.

Holmdel Community Church U.C.C. Complex
40 Main St., Holmdel, Monmouth County, N.J.
Photographer: Edward B. Schumacher
Negatives: from color slide included in nomination

View: from north end of Sanctuary crawl space, looking north

#3 of 24 - stone foundation wall at north end of original church location (mortar applied about 1970)



Holmdel Community Church U.C.C. Complex
40 Main St., Holmdel, Monmouth County, N.J.
Photographer: Edward B. Schumacher
Negatives: from color slide included in nomination

View: from west side of Sanctuary crawl space, looking west

#4 of 24 - examples of Sanctuary floor joist piers, a stone and oak tree trunk segment (left), and a length of locust log (right).

Holmdel Community Church U.C.C. Complex
40 Main St., Holmdel, Monmouth County, N.J.
Negatives: Dankwart Koehler
View: in Narthex, looking west
#5 of 24 - Narthex

Holmdel Community Church U.C.C. Complex
40 Main St., Holmdel, Monmouth County, N.J.
Negatives: Dankwart Koehler
View: from balcony, of Sanctuary
#6 of 24 - south view of Sanctuary

16
173

Holmdel Community Church U.C.C. Complex
40 Main St., Holmdel, Monmouth County, N.J.
Negatives: Dankwart Koehler
View: from center aisle of Sanctuary
#7 of 24 - south wall of Sanctuary

Holmdel Community Church U.C.C. Complex
40 Main St., Holmdel, Monmouth County, N.J.
Negatives: Dankwart Koehler
View: from center aisle
#8 of 24 - Altar and Choir

Holmdel Community Church U.C.C. Complex
40 Main St., Holmdel, Monmouth County, N.J.
Negatives: Dankwart Koehler
View: from southeast corner of Sanctuary
#9 of 24 - north view of Sanctuary



Holmdel Community Church U.C.C. Complex
40 Main St., Holmdel, Monmouth County, N.J.
Negatives: Dankwart Koehler
View: looking at east wall of Sanctuary
#10 of 24 - Stained glass windows



Holmdel Community Church U.C.C. Complex
40 Main St., Holmdel, Monmouth County, N.J.
Photographer: Edward B. Schumacher
Negatives: Holmdel Community Church
1986

View: from north end of Sanctuary attic, looking south

#11 of 24 - typical pinned mortise and tenon joint connecting hewn center column and rafter elements at ridge line of roof truss



Holmdel Community Church U.C.C. Complex
40 Main St., Holmdel, Monmouth County, N.J.
Photographer: Edward B. Schumacher
Negatives: Holmdel Community Church
1986

View: from north end of Sanctuary attic, looking southeast

#12 of 24 - roof truss diagonal brace and center column arrangement

Holmdel Community Church U.C.C. Complex
40 Main St., Holmdel, Monmouth County, N.J.
Photographer: Edward B. Schumacher
Negatives: Holmdel Community Church
1986

View: from north end of Sanctuary attic

#13 of 24 - roof truss diagonal brace and center column connection

Holmdel Community Church U.C.C. Complex
40 Main St., Holmdel, Monmouth County, N.J.
Photographer: Edward B. Schumacher
Negatives: Holmdel Community Church
1986

View: looking west toward roof in Sanctuary attic

#14 of 24 - roof truss detail where diagonal brace and outboard column are connected to roof rafter

Holmdel Community Church U.C.C. Complex
40 Main St., Holmdel, Monmouth County, N.J.
Photographer: Edward B. Schumacher
Negatives: Holmdel Community Church
1986

View: looking west toward eave in Sanctuary attic

#15 of 24 - roof truss bottom chord and roof rafters at eave line, showing wood strut supports for perimeter of ceiling and loose ceiling insulation

Holmdel Community Church U.C.C. Complex
40 Main St., Holmdel, Monmouth County, N.J.
Negatives: Dankwart Koehler
View: from across Main St.
#16 of 24 - Parsonage, Hall, and Church

ADULT DAY
CENTER

Holmdel Community Church U.C.C. Complex
40 Main St., Holmdel, Monmouth County, N.J.
Negatives: Dankwart Koehler
View: from across Main St.
#17 of 24 - Hall

Holmdel Community Church U.C.C. Complex
40 Main St., Holmdel, Monmouth County, N.J.
Negatives: Dankwart Koehler
View: from across Main St.
#18 of 24 - Church, front facade & steeple

Holmdel Community Church U.C.C. Complex
40 Main St., Holmdel, Monmouth County, N.J.
Negatives: Dankwart Koehler
View: from across Main St.
#19 of 24 - Church, front facade


Community Church
United Church
Of Christ

Holmdel Community Church U.C.C. Complex
40 Main St., Holmdel, Monmouth County, N.J.
Negatives: Dankwart Koehler
View: from across Main St.
#20 of 24 - Church, southwest view

Holmdel Community Church U.C.C. Complex
40 Main St., Holmdel, Monmouth County, N.J.
Negatives: Dankwart Koehler
View: from across Main St.
21 of 24 - Parsonage

BAPTIST CHURCH
ORGANIZED 1888
REMODELED 1893

Holmdel Community Church U.C.C. Complex
40 Main St., Holmdel, Monmouth County, N.J.
Negatives: Dankwart Koehler
View: from front of Church
#22 of 24 - Church, front entrance

Holmdel Community Church U.C.C. Complex
40 Main St., Holmdel, Monmouth County, N.J.
Negatives: Dankwart Koehler
View: from Church parking lot
#23 of 24 - back of Church, Hall & Parsonage

Holmdel Community Church U.C.C. Complex
40 Main St., Holmdel, Monmouth County, N.J.
Negatives: Dankwart Koehler
View: from northwest corner of cemetery
#24 of 24 - Church cemetery