

Charles William Boyd photo, 1981 20160 Tumalo Road Bend, OR 97701

l of 7 General view of ensemble from Rivermall Avenue. Camera facing north.



Charles William Boyd photo, 1981 20160 Tumalo Road Bend, OR 97701

2 of 7 South elevation of Ranch house. Picture window was added in end wall of living room in the 1950s. It may be reversed.



Charles William Boyd photo, 1981 20160 Tumalo Road Bend, OR 97701

3 of 7 North elevation of Ranch house showing semi-enclosed porch off bathroom-kitchen wing of 1914.



Charles William Boyd photo, 1981 20160 Tumalo Road Bend, OR 97701


4 of 7 Bunk house, south and east elevations.



Charles William Boyd photo, 1981 20160 Tumalo Road Bend, OR 97701


5 of 7 West elevation of Ranch house and bunk house, showing pineshaded site. The original front door opening was filled

in when the kitchen wing was added in 1914.



Charles William Boyd photo, 1981 20160 Tumalo Road Bend, OR 97701

6 of 7 Ice house, south and east elevations.



Charles William Boyd photo, 1981 20160 Tumalo Road Bend, OR 97701

7 of 7 Ice house, north and west elevations.