



Name: Agricultural Buildings and Complexes in Mill Creek
Hundred, 1800-1840, S. P. Dixon Farm (N-4072)

Location: Wooddale Road, Greenville, Delaware 19807

Photographer: Valerie Cesna

Date: June 1986

Location of Negative: Bureau of Archaeology and Historic
Preservation, Dover, Delaware

Description: Dwelling, view from northwest

Photograph Number: 19



Name: Agricultural Buildings and Complexes in Mill Creek
Hundred, 1800-1840, S. P. Dixon Farm (N-4072)

Location: Wooddale Road, Greenville, Delaware 19807

Photographer: Valerie Cesna

Date: June 1986

Location of Negative: Bureau of Archaeology and Historic
Preservation, Dover, Delaware

Description: Dwelling, view from south

Photograph Number: 20



Name: Agricultural Buildings and Complexes in Mill Creek
Hundred, 1800-1840, S. P. Dixon Farm (N-4072)

Location: Wooddale Road, Greenville, Delaware 19807

Photographer: Valerie Cesna

Date: June 1986

Location of Negative: Bureau of Archaeology and Historic
Preservation, Dover, Delaware

Description: Barn, view from northwest

Photograph Number: 21