



Falling Spring Complex
Falling Spring House

SHEPHERDSTOWN, Jeff-
erson Co.
W.VA.

By: Diana Suttentfield
Abshire

Spring 1989

FRONT (N) ELEV.

PHOTO 1 OF 12

PROPERTY NAME: FALLING SPRING
LOCATION: SHEPHERDSTOWN
WEST VIRGINIA

PHOTO CREDIT: DIANA SUTTENTFIELD-ABSHIRE
DATE OF PHOTO: SPRING 1989
NEGATIVE FILED AT: DEPT. OF CULTURE & HISTORY, HISTORIC PRESERVATION UNIT,
THE CULTURAL CENTER, CAPITOL COMPLEX, CHARLESTON, WV 25305
DESCRIPTION OF PHOTO:
NORTH FRONT / PORCH DETAILS -
GROUND FLOOR / CRAWL SPACE / LATTICE

DIRECTION OF PHOTO:



Falling Spring Complex
Falling Spring House

SHEPHERDSTOWN, Jefferson
CO., W.VA.

By: Diana Suttentfield
Abshire

Spring 1987

North Portico Detail

Front (N.) ELEV.

PHOTO 2 OF 12

PROPERTY NAME: FALLING SPRING
LOCATION: SHEPHERDSTOWN
WEST VIRGINIA

PHOTO CREDIT: DIANA SUTTENFIELD-ABSHIRE
DATE OF PHOTO: SPRING 1987
NEGATIVE FILED AT: DEPT. OF CULTURE & HISTORY, HISTORIC PRESERVATION UNIT,
THE CULTURAL CENTER, CAPITOL COMPLEX, CHARLESTON, WV 25305
DESCRIPTION OF PHOTO:

NORTH PORCH / PORTICO
FRONT DOOR, 2nd FLOOR BALCONY
DIRECTION OF PHOTO:



1911 03 01 10:00 AM

Falling Spring Complex

Falling Spring House

SHEPHERDSTOWN vic, Jefferson
Co., W.VA.

Side (W.) ELEV., ALSO N. FACADE

By: DIANA SUTTENFIELD ABSHIRE
Spring 1987

PHOTO 3 OF 12

PROPERTY NAME: FALLING SPRING
LOCATION: SHEPHERDSTOWN
WEST VIRGINIA

PHOTO CREDIT: DIANA SUTTENFIELD-ABSHIRE
DATE OF PHOTO: SPRING 1987
NEGATIVE FILED AT: DEPT. OF CULTURE & HISTORY, HISTORIC PRESERVATION UNIT,
THE CULTURAL CENTER, CAPITOL COMPLEX, CHARLESTON, WV 25305

DESCRIPTION OF PHOTO:
WEST SIDE OF MAIN HOUSE
(PARTIAL NORTH SIDE)
MOUNTING BLOCK TO FAR RIGHT
DIRECTION OF PHOTO:

SOUTH WEST

OCT 20 1988



FALLING SPRING COMPLEX
FALLING SPRING HOUSE
SHEPHERDSTOWN VIC., Jefferson
CO., W.VA.

Detail N. DOOR

By: Diana Suttentfield Abshire
Spring 1987

PHOTO 4 OF 12

PROPERTY NAME: FALLING SPRING
LOCATION: SHEPHERDSTOWN
WEST VIRGINIA

PHOTO CREDIT: DIANA SUTTENTFIELD-ABSHIRE
DATE OF PHOTO: SPRING 1987
NEGATIVE FILED AT: DEPT. OF CULTURE & HISTORY, HISTORIC PRESERVATION UNIT,
THE CULTURAL CENTER, CAPITOL COMPLEX, CHARLESTON, WV 25305
DESCRIPTION OF PHOTO:

DETAIL OF FRETWORK / FRONT DOOR
ON NORTH SIDE -
DIRECTION OF PHOTO:

OCT 20 1988



FALLING SPRING COMPLEX
FALLING SPRING HOUSE
SHEPHERDSTOWN VIC., Jefferson
Co., W.VA.

DETAIL N. FRONT DOOR

By: DIANA SUTTENFIELD ABSHIRE
SPRING 1987

PHOTO 5 OF 12

PROPERTY NAME: FALLING SPRING
LOCATION: SHEPHERDSTOWN
WEST VIRGINIA

PHOTO CREDIT: DIANA SUTTENFIELD-ABSHIRE
DATE OF PHOTO: SPRING 1987
NEGATIVE FILED AT: DEPT. OF CULTURE & HISTORY, HISTORIC PRESERVATION UNIT,
THE CULTURAL CENTER, CAPITOL COMPLEX, CHARLESTON, WV 25305
DESCRIPTION OF PHOTO:

NORTH FACING FRONT DOOR

DIRECTION OF PHOTO:
NORTH



FALLING SPRING COMPLEX

FALLING SPRING HOUSE

SHEPHERDSTOWN VIC., Jefferson Co.,
W.VA.

INTERIOR STAIR DETAIL

By: DIANA SUTTENFIELD ABSHIRE

Spring 1987

PHOTO 6 OF 12

PROPERTY NAME: FALLING SPRING
LOCATION: SHEPHERDSTOWN
WEST VIRGINIA

PHOTO CREDIT: DIANA SUTTENFIELD-ABSHIRE
DATE OF PHOTO: SPRING 1987
NEGATIVE FILED AT: DEPT. OF CULTURE & HISTORY, HISTORIC PRESERVATION UNIT,
THE CULTURAL CENTER, CAPITOL COMPLEX, CHARLESTON, WV 25305
DESCRIPTION OF PHOTO:
LOOKING UP FRONT 1ST FLOOR LANDING TO THE
SECOND FLOOR ~
DIRECTION OF PHOTO:



FALLING SPRING COMPLEX
SHEPHERDSTOWN, Jefferson Co., W.VA.
SHEPHERDSTOWN vic.

SPRING
1987

BY: DIANA SUTTENFIELD ABSHIRE
DINING ROOM DETAIL
PHOTO 7 OF 12

PROPERTY NAME: FALLING SPRING
LOCATION: SHEPHERDSTOWN
WEST VIRGINIA

PHOTO CREDIT: DIANA SUTTENFIELD-ABSHIRE
DATE OF PHOTO:
NEGATIVE FILED AT: DEPT. OF CULTURE & HISTORY, HISTORIC PRESERVATION UNIT,
THE CULTURAL CENTER, CAPITOL COMPLEX, CHARLESTON, WV 25305
DESCRIPTION OF PHOTO:
DINING ROOM FIRE PLACE/MANTEL

DIRECTION OF PHOTO:
EAST

OCT 20 1988



FALLING SPRING COMPLEX

SHEPHERDSTOWN VIC.

Jefferson Co., W.VA.

MEATHOUSE

PHOTO BY: DIANA SUTTENFIELD

PHOTO 8 OF 12

LOOKING

N.

PROPERTY NAME: FALLING SPRING
LOCATION: SHEPHERDSTOWN
WEST VIRGINIA

PHOTO CREDIT: DIANA SUTTENFIELD-ARSMIRE
DATE OF PHOTO: SPRING 1987
NEGATIVE FILED AT: DEPT. OF CULTURE & HISTORY, HISTORIC PRESERVATION UNIT,
THE CULTURAL CENTER, CAPITOL COMPLEX, CHARLESTON, WV 25305
DESCRIPTION OF PHOTO:

BRICK SMOKE HOUSE
BRICK COLONADE / PART KITCHEN WING

DIRECTION OF PHOTO:

NORTH

OCT 20 1988



FALLING SPRING COMPLEX
SHEPHERDSTOWN, Jefferson Co.,
W.VA.

COTTAGE Spring 1987

By: DIANA SUTTENFIELD ABSHIRE

LOOKING E

PHOTO 9 OF 12

PROPERTY NAME: FALLING SPRING
LOCATION: SHEPHERDSTOWN
WEST VIRGINIA

PHOTO CREDIT: DIANA SUTTENFIELD-ABSHIRE
DATE OF PHOTO: ~~FALL~~ SPRING 1987

NEGATIVE FILED AT: DEPT. OF CULTURE & HISTORY, HISTORIC PRESERVATION UNIT,
THE CULTURAL CENTER, CAPITOL COMPLEX, CHARLESTON, WV 25305

DESCRIPTION OF PHOTO:
"VIRGINIA COTTAGE"

DIRECTION OF PHOTO:
EAST

OCT 20 1988



FALLING SPRING COMPLEX
SHEPHERDSTOWN VIC., Jefferson Co.,
W. VA.

GARAGE

By: RODNEY COLLINS

AUGUST 1988

PHOTO 10 OF 12



1900

FALLING SPRING COMPLEX
SHEPHERDSTOWN vic., Jefferson Co.,
W. VA.

OLD STONE HOUSE

LOOKING N.

By: RODNEY S. COLLINS

August 1988

PHOTO 11 OF 12



FALLING SPRING COMPLEX
SHEPHERDSTOWN, JEFFERSON CO.,
W.VA.

MORGAN'S SPRING
LOOKING N.

By: RODNEY S. COLLINS

AUG. 1988

PHOTO 12 OF 12

OCT 20 1988