



1. Williamson House
2. Grafton, North Dakota
3. Photographer: Unknown
4. Date: Unknown, published in City of Grafton, 1900
5. Negative Location: State Historical Society of ND  
Heritage Center  
Bismarck ND 58505
6. Facade from south
7. Photograph 1/19



1. Williamson House
2. Grafton, North Dakota
3. Photographer: Patricia Jessen
4. Date: May 18, 1984
5. Negative Location: Cultural Research & Management  
P.O. Box 2154  
Bismarck, ND 58502
6. Facade from south
7. Photograph 2/19



1. Williamson House
2. Grafton, North Dakota
3. Photographer: Kurt P. Schweigert
4. Date: July, 1980
5. Negative Location: State Historical Society of ND  
Heritage Center  
Bismarck, ND 58505
6. Exterior of house from southwest
7. Photograph 3/19



1. Williamson House
2. Grafton, North Dakota
3. Photographer: Kurt P. Schweigert
4. Date: July, 1980
5. Negative Location: State Historical Society of ND  
Heritage Center  
Bismarck, ND
6. Exterior of house from SE
7. Photograph 4/19





1. Williamson House
2. Grafton, North Dakota
3. Photographer: Kurt P. Schweigert
4. Date: July, 1980
5. Negative Location: State Historical Society of ND  
Heritage Center  
Bismarck, ND 58505
6. Exterior of house & porch addition from NW
7. Photograph 5/19



1. Williamson House
2. Grafton, North Dakota
3. Photographer: Kurt P. Schweigert
4. Date: July, 1980
5. Negative Location: State Historical Society of ND  
Heritage Center  
Bismarck, ND 58505
6. Exterior of house & carport from NE
7. Photograph 6/19



1. Williamson House
2. Grafton, North Dakota
3. Photographer: Kurt P. Schweigert
4. Date: July, 1980
5. Negative Location: State Historical Society of ND  
Heritage Center  
Bismarck, ND 58505
6. Exterior of house from NE
7. Photograph 7/19



1. Williamson House
2. Grafton, North Dakota
3. Photographer: Kurt P. Schweigert
4. Date: July, 1980
5. Negative Location: State Historical Society of ND  
Heritage Center  
Bismarck, ND 58505
6. Exterior of Garage from NW
7. Photograph 8/19





1. Williamson House
2. Grafton, North Dakota
3. Photographer: Patricia Jessen
4. Date: May 18, 1984
5. Negative Location: Cultural Research & Management  
P.O. Box 2154  
Bismarck, ND 58502
6. House & grounds from SE (from across Park River)
7. Photograph 9/19



1. Williamson House
2. Grafton, North Dakota
3. Photographer: Patricia Jessen
4. Date: May 18, 1984
5. Negative Location: Cultural Research & Management  
P.O. Box 2154  
Bismarck, ND 58502
6. Front stairway & window with stained glass from SE
7. Photograph 10/19



1. Williamson House
2. Grafton, North Dakota
3. Photographer: Patricia Jessen
4. Date: May 18, 1984
5. Negative Location: Cultural Research & Management  
P.O. Box 2154  
Bismarck ND 58502
6. Dining room & entrance hallway from north
7. Photograph 11/19



1. Williamson House
2. Grafton, North Dakota
3. Photographer: Patricia Jessen
4. Date: May 18, 1984
5. Negative Location: Cultural Research & Management  
P.O. Box 2154  
Bismarck, ND 58502
6. Dining room window with stained glass from SE
7. Photograph 12/19





1. Williamson House
2. Grafton, North Dakota
3. Photographer: Patricia Jessen
4. Date: May 18, 1984
5. Negative Location: Cultural Research & Management  
P.O. Box 2154  
Bismarck, ND 58502
6. Living room from NW
7. Photograph 13/19



1. Williamson House
2. Grafton, North Dakota
3. Photographer: Patricia Jessen
4. Date: May 18, 1984
5. Negative Location: Cultural Research & Management  
P.O. Box 2154  
Bismarck, ND 58502
6. Living room from SE
7. Photograph 14/19



1. Williamson House
2. Grafton, North Dakota
3. Photographer: Patricia Jessen
4. Date: May 18, 1984
5. Negative Location: Cultural Research & Management  
P.O. Box 2154  
Bismarck, ND 58502
6. Fireplace from SW
7. Photograph 15/19



1. Williamson House
2. Grafton, North Dakota
3. Photographer: Patricia Jessen
4. Date: May 18, 1984
5. Negative Location: Cultural Research & Management  
P.O. Box 2154  
Bismarck, ND 58502
6. Kitchen from NE
7. Photograph 16/19






1. Williamson House
2. Grafton, North Dakota
3. Photographer: Patricia Jessen
4. Date: May 18, 1984
5. Negative location: Cultural Research & Management  
P.O. Box 2154  
Bismarck, ND 58502
6. Servants stairs from north
7. Photograph 17/19



1. Williamson House
2. Grafton, North Dakota
3. Photographer: Patricia Jessen
4. Date: May 18, 1984
5. Negative location: Cultural Research & Management  
P.O. Box 2154  
Bismarck, ND 58502
6. Detail of hand-graining from North
7. Photograph 18/19



1. Williamson House
2. Grafton, North Dakota
3. Photographer: Patricia Jessen
4. Date: May 18, 1984
5. Negative location: Cultural Research & Management  
P.O. Box 2154  
Bismarck, ND 58502
6. Stained glass window in bedroom from west
7. Photograph 19/19



Williamson House

Grafton, ND

Photo Credit: Unknown

Date: ca. 1915

Negative Location: State Historical Society of ND  
Heritage Center  
Bismarck, ND 58505

View: Part of Facade Porch from SE

Photo:





Williamson House

Grafton, ND

Photo Credit: Unknown

Date: ca. 1945

Negative Location: State Historical Society of ND  
Heritage Center  
Bismarck, ND 58505

View: Facade and East Elevation from SE

Photo:



Williamson House

Grafton, ND

Photo Credit: Unknown

Date: ca. 1945

Negative Location: State Historical Society of ND  
Heritage Center  
Bismarck, ND 58505

View: North and West Elevations from NW

Photo:



Williamson House

Grafton, ND

Photo Credit: Unknown

Date: ca. 1949

Negative Location: State Historical Society of ND  
Heritage Center  
Bismarck, ND

View: Facade from South

Photo:



Williamson House

Grafton, ND

Photo Credit: Unknown

Date: 1950

Negative Location: State Historical Society of ND  
Heritage Center  
Bismarck, ND 58505

View: Facade & East Elevation from SE

Photo: