

KENTUCKY HISTORIC RESOURCES INVENTORY

Site No. Wd-75

1. Historic Name(s) <u>Robertson place</u>		22. ADD/County <u>Beargrass, Woodford</u>	
Original Owner		23. U.S.G.S. Quadrant (15'/75') <u>Zone 16 Easting 692240 Northing 4216450</u>	
2. Present Name <u>Robertson place</u>		24. UTM Reference	
3. Location <u>W.W. Lee Clipson and Steele Pike</u>		25. Coordinate Accuracy	
4. Owner's Name <u>Henry Leadley</u>		26. Prehistoric Site <input type="checkbox"/>	
5. Owner's Address <u>Steele Pike, Versailles, Ky. 40383</u>		Historic Site <input type="checkbox"/>	
6. Open to Public Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		Building <input checked="" type="checkbox"/>	
7. Visible from road Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>		Other <input type="checkbox"/>	
9. Local Contact/Organization		27. National Register District Name:	
10. Site Plan with North Arrow <u>see attached boundary form</u>		28. Significance Evaluation <input type="checkbox"/>	
11. Architect		29. Status	
12. Builder		National Landmark <input type="checkbox"/> Date	
13. Date <u>1st 1/4 19th C.A. [2]</u> B. <input type="checkbox"/>		National Register <input type="checkbox"/>	
14. Style		Landmark Certificate <input type="checkbox"/>	
A. <u>Federal</u> <input checked="" type="checkbox"/>		Kentucky Survey <input type="checkbox"/>	
B. <input type="checkbox"/>		Local Landmark <input type="checkbox"/>	
15. Original Use <u>residence</u> <input checked="" type="checkbox"/>		HABS/HAER <input type="checkbox"/>	
16. Present use <u>residence</u>		30. Historic Theme	
17. Condition <u>excellent</u> <input checked="" type="checkbox"/>		Primary <u>architecture</u> <input checked="" type="checkbox"/>	
18. Description		Secondary <input type="checkbox"/>	
No. Stories <u>1 3/4</u> <input checked="" type="checkbox"/>		Other <input type="checkbox"/>	
Single Pile <input type="checkbox"/> NA <input type="checkbox"/>		31. Endangered Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	
Double Pile <input checked="" type="checkbox"/>		32. Preservation Project Status <input type="checkbox"/>	
Floor Plan <u>double pile central passage</u> <input checked="" type="checkbox"/>		Actual Cost in \$1,000s	
Structural Fabric <u>stone/frame</u> <input checked="" type="checkbox"/> B. <input type="checkbox"/>		33. ATTACH PHOTO <u>in attached envelope</u>	
Decorative Fabric <u>ashlar masonry</u> A. <input checked="" type="checkbox"/>		Roll No. _____	
B. <input checked="" type="checkbox"/>		Picture No. _____	
Roof Form <u>gable</u>		Direction _____	
19. History <u>not researched</u>		34. Prepared by: <u>Carolyn M. Wooley</u>	
<u>1877: S. H. Robertson</u>		35. Organization _____	
20. Significance <u>unique use of stone and frame in double pile house.</u>		36. Date <u>1982</u>	
21. Source of Information <u>inspection</u>		37. Revision Dates _____	
		38. Staff Review _____	

18. cont. :

(owner believes all constructed at same time, according to roof framing system); all wood frame and trim now covered w. aluminum.

Fine quality stonework, best on front. Log building in back yard. Spring house in front. Porch spans rear.

STONE HOUSE SURVEY
BOUNDARY INFORMATION FORM

SITE # Wd - 75
SITE NAME Robertson place

VERBAL BOUNDARY DESCRIPTION & JUSTIFICATION

Beginning at A at the corner of Clifton and Seale Pikes, thence W with Clifton Pike 530 to B, thence N 530 ft to C, ~~at~~ at the Seale Pike, thence west road to the beginning, containing the house, barn, log smoke house, spring house, pond & driveway. 6 1/2 acres

SKETCH MAP OF SITE SHOWING BOUNDARIES AND KEY BUILDINGS AND FEATURES WITH NORTH ARROW.

