

Looking southerly, the northeasterly facade and the northwesterly side elevation of Roseland.

Photo credit: Dr. Orrin James, February 1985.

# Photo 1 of $4^{\circ}$



Looking northerly, the southwesterly rear elevation and the southeasterly side elevation of Roseland.

Photo credit: Dr. Orrin James, February 1985.

Photo 2 of 4



Looking easterly, the southern rear room showing the mantel piece and original closet.

Photo credit: Dr. Orrin James, February 1985.

Photo 3 of 4



Looking northerly, toward the entrance doorway from the rear of the main hallway showing the doorway trim and keystoned arch. Plaster removed prior to relocation.

Photo credit: Dr. Orrin James, February 1985.

Photo 4 of 4