



Torréns Bridge

State Road #319 Km. 1.51

Hormigueros, P.R.

Alex Rosa

Nov 1989

Negative file S.H.P.O. (T-27, 28)

View of the bottom of the deck or
floor and the southern abutment

(see the floor steel beams and
the stones and bricks abutment
in the south bank of the
Rosario River)

Photo #1



Torrens Bridge

State Road #319 Km. 1.51

Hormigueros, P.R.

Alex Rosa

Nov 1989

Negative file S.H.P.O. (T-29

View of the eastern "baranda"

(steel lattice girder). Facing approximately south.

Photo #2

(jungle).



Torrens Bridge
Hormigueros, Puerto Rico

José E. Marull

1997

PRSHPO

View of western "baranda". Camera facing north.

Photo # 3



Torrens Bridge
Hormigueros, Puerto Rico

José E. Marull

1997

PRSHPO

View of the roadway over the bridge. Camera facing east.

Photo # 4