

Torrens Bridge
State Road #319 Km. 1.51
Hormigueros, P.R.

Alex Rosa

Nov 1989

Negative file S.H.P.O. (T-27, 28)
View of the bottom of the deck or floor and the southern abutment (see the floor steel beams and the stones and bricks abutment in the south bank of the Rosario River)

Photo #1

Torrens Bridge
State Road #319 Km. 1.51
Hormigueros, P.R.

Alex Rosa

Nov 1989

Negative file S.H.P.O. (T-29

View of the eastern "baranda"
(steel lattice girder). Facing approximately south.

Photo #2

Torrens Bridge
Hormigueros, Puerto Rico
José E. Marull
1997
PRSHPO
View of western "baranda". Camara facing north.
Photo #3

Torrens Bridge
Hormigueros, Puerto Rico
José E. Marull
1997
PRSHPO
View of the roadway over the bridge. Camara facing east.
Photo #4