



NOV 28 1978

Smithfield Lower Meetinghouse.
Smithfield Avenue
Lincoln, Rhode Island

Photograph by: Warren Jagger
Negative at: R.I. Historical Preservation Commission
150 Benefit St.
Providence, R.I.

Smithfield Lower Meetinghouse, seen from southwest;
1704 section on left, c. 1745 section on right.

Photograph #1

OCT 10 1978



NOV 28 1978

Smithfield Lower Meetinghouse
Smithfield Avenue
Lincoln, Rhode Island

OCT 10 1978

Photograph by: Warren Jagger
Negative at: R.I. Historical Preservation Commission
150 Benefit St.
Providence, R.I.

Smithfield Lower Meetinghouse, seen from northwest corner of 1704 section and showing door of 1704 section, wall separating two sections, and interior of c. 1745 section.

Photograph #2



NOV 28 1978

Smithfield Lower Meetinghouse
Smithfield Avenue
Lincoln, Rhode Island

Photograph by: Warren Jagger
Negative at: Rhode Island Historical Preservation
Commission
150 Benefit St., Providence, R.I.

Smithfield Lower Meetinghouse, seen from southeast
corner of c. 1745 section and showing framing and gallery
gallery (now closed off).

Photograph #3

OCT 10 1978



NOV 28 1978

OCT 10 1978

Smithfield Lower Meetinghouse
Smithfield Avenue
Lincoln, Rhode Island

Photograph by: Warren Jagger
Negative at: R.I. Historical Preservation Commission
150 Benefit St.
Providence, R.I.

Smithfield Lower Meetinghouse; west end of gallery
(now closed), showing framing.

Photograph #4