



Cook-Bateman Farm
Tiverton, Rhode Island

Photographer: Warren Jagger January, 1979
Negative: Rhode Island Historical Preservation
Commission

View of the house from the south-southwest,
showing original south facade (with porch)
and western flank with doorway added.

Photo #1

OCT 11 1979

AUG 7 1979



Cook-Bateman Farm
Tiverton, Rhode Island

Photographer: Warren Jagger January, 1979
Negative: Rhode Island Historical Preservation
Commission

View of the house from the east, showing porch
added in the 20th century, rear ell, and a
portion of an early 18th century outbuilding.

Photo #2

AUG 7 1979

OCT 11 1979



Cook-Bateman Farm
Tiverton, Rhode Island


Photographer: Warren Jagger January, 1979
Negative: Rhode Island Historical Preservation
Commission

View northeast across the farm, from the
east porch; showing barn at left, outhouse,
long shed, stone walls, fields, and salt pond.

Photo #3

OCT 11 1979

AUG 7 1979



Cook-Bateman Farm
Tiverton, Rhode Island

Photographer: Warren Jagger January, 1979
Negative: Rhode Island Historical Preservation
Commission


View of the (apparently) intact fireplace wall
of the southwest parlor; note cornice, panelling,
and Aesop's Fables tiles in fireplace surround.

Photo #4

OCT 11 1979

AUG 7

1979



Cook-Bateman Farm
Tiverton, Rhode Island

Photographer: Warren Jagger January, 1979
Negative: Rhode Island Historical Preservation
Commission

View of the southeast parlor, showing relocated
chimney breast woodwork, Federal firefront,
paneled dado, and late 19th century or early
twentieth century window and door alterations;
looking northeast.

AUG 7 1979 Photo #5

OCT 11 1979



Cook-Bateman Farm
Tiverton, Rhode Island

Photographer: Warren Jagger January, 1979
Negative: Rhode Island Historical Preservation
Commission

Pantry behind (north of) southwest parlor,
probably late 18th century or early 19th cen-
tury with later copper counter and sink;
looking west.

Photo #6

OCT 11 1979

AUG 7 1979

Photo #6



Cook-Bateman Farm
Tiverton, Rhode Island

Photographer: Warren Jagger January, 1979
Negative: Rhode Island Historical Preservation
Commission

Looking east in southwest chamber.

Photo #7

Photo #7

AUG 7 1979

OCT 11 1979