

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

FOR NPS USE ONLY
RECEIVED JUL 8 1975

DATE ENTERED AUG 2 2 1975

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS

TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

1	N	Al	V	E
	1 7	4 14	VД	

HISTORIC

Crawford Building

AND/OR COMMON

LOCATION

CITY, TOWN

_VICINITY OF

COUNTY

STATE

Topeka

Shawnee

Kansas

3 PHOTO REFERENCE

PHOTO CREDIT Richard Pankratz

DATE OF PHOTO 1974

NEGATIVE FILED AT

Historic Sites Survey, Kansas State Historical Society

IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

View of the Crawford Building from the east showing the front as it looked after being cleaned but before all broken windows had been replaced.



UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

FOR NPS USE ONLY
RECEIVED JUL 8 1975
DATE ENTERED AUG 2 2 1975

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS

TYPE ALL ENTRIES -- LENCLOSE WITH PHOTOGRAPH

1 NAME

HISTORIC

Crawford Building

AND/OR COMMON

2 LOCATION

CITY, TOWN

__VICINITY OF

COUNTY

STATE

Topeka

Shawnee

Kansas

3 PHOTO REFERENCE

PHOTO CREDIT Richard Pankratz

DATE OF PHOTO

1974

NEGATIVE FILED AT

Historic Sites Survey, Kansas State Historical Society

4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

View of the Crawford Building from the northwest showing the north side.



UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

FOR NP	SUSE	ONLY			
RECEIV	ED J	UL 8	197	5	
DATE EI		. Alle	9 9 1	975	
DATEE	MESIE) wod	N N	310	

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL I	REGISTER .	FORMS
TYPE ALL ENTRIES ENCLOSE WITH PH	OTOGRADI	ш

1	NAME
1	TALFIATE

HISTORIC

Crawford Building

AND/OR COMMON

2 LOCATION

CITY, TOWN

_VICINITY OF

COUNTY

STATE

Topeka

Shawnee

Kansas

3 PHOTO REFERENCE

PHOTO CREDIT Richard Pankratz

DATE OF PHOTO

1974

NEGATIVE FILED AT

Historic Sites Survey, Kansas State Historical Society

4 IDENTIFICATION

DESCRIBE VIEW. DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

PHOTO NO. 3

View of the west wall from the northwest showing the spiral fire escape stairs.



UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

FOR NPS USE ONLY JUL 8 1975 RECEIVED AUG 2 2 1975 DATE ENTERED

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS TYPE ALL ENTRIES -- IENCLOSE WITH PHOTOGRAPH

	NT	AB	ATC
1	IN.	AN	/IL

HISTORIC

Crawford Building

AND/OR COMMON

LOCATION

CITY, TOWN Topeka

VICINITY OF

COUNTY Shawnee

STATE Kansas

PHOTO REFERENCE

PHOTO CREDIT Richard Pankratz

1974 **DATE OF PHOTO**

NEGATIVE FILED AT

Historic Sites Survey, Kansas State Historical Society

IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

Close-up of the decorative terra cotta at the east entrance.

PROPERTY OF THE NATIONAL RESISTER

PHOTO NO.



UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

FOR NPS USE ONLY RECEIVED JUL 8 1975 DATE ENTERED AUG 2 2 1975

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

1 NAME

HISTORIC

Crawford Building

AND/OR COMMON

LOCATION

CITY, TOWN

VICINITY OF

COUNTY

STATE

Topeka

Shawnee

Kansas

PHOTO REFERENCE

PHOTO CREDIT Richard Pankratz

DATE OF PHOTO 1974

NEGATIVE FILED AT

Historic Sites Survey, Kansas State Historical Society

IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

PHOTO NO. 5

View of the area directly above the east entrance showing the metal balcony and fire escape on the second floor and the decorative terra cotta beneath it.



UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

FOR MPS USE ONLY

RECEIVED JUL 8 1975

DATE ENTERED AUG 2 2 1975

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS

TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

1 NAME

HISTORIC Crawford Building

AND/OR COMMON

2 LOCATION

CITY, TOWN Topeka _VICINITY OF

COUNTY

STATE Kansas

3 PHOTO REFERENCE

PHOTO CREDIT Eric Kjorlie

DATE OF PHOTO Jan. 10, 1975

NEGATIVE FILED AT


Eric Kjorlie, Topeka, Kan.

4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

PHOTO NO.

View from the northeast showing the east and north facades of the Crawford Building.



UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

·////

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS

TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

NAME
TAVIATE

HISTORIC

Crawford Building

AND/OR COMMON

2 LOCATION

CITY. TOWN Topeka VICINITY OF

COUNTY

STATE

Shawnee Kansas

3 PHOTO REFERENCE

PHOTO CREDIT unknown

DATE OF PHOTO

c. 1888

NEGATIVE FILED AT

Photo Archives, Kansas State Historical Societ

У

4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

PHOTO NO.

View from the east showing the Crawford Building soon after completion. This view was copied from The Capital City: Topeka, Picturesque and Descriptive (Neenah, Wisc., Art Publishing Co., 1888-1889).



UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

FOR NPS USE	ONLY			
RECEIVED JU	LO	1975		
DATE ENTERS	. Al	JG 22	1975	

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS TYPE ALL ENTRIES -- IENCLOSE WITH PHOTOGRAPH

1 NAME

HISTORIC

Crawford Building

AND/OR COMMON

2 LOCATION

CITY, TOWN Topeka VICINITY OF

COUNTY

STATE

Kansas

3 PHOTO REFERENCE

PHOTO CREDIT unknown

DATE OF PHOTO

c. 1900

NEGATIVE FILED AT

Photo Archives, Kansas State Historical Society

4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

PHOTO NO. 8

View from the northeast showing the east and northsides of the Crawford Building.

The capitals atop the pilasters were still intact at that time.