



1. Camp No.1. Dam, view looking  
north and down-  
stream.

MAR 1 1978

DEC 12 1978



2. Camp No.1. Dam, view looking  
west.

MAR 1 1978

DEC 12 1978



3. Camp No.1. Building No.2,  
view looking west  
at entrance.

MAR 1 1978

DEC 12 1978



DEC 12 1978

4. Flume remains showing construction detail, especially bracing of the trough. Located between Camps No.1 and No.2.

MAR 1 1978





5. Flume remains showing bracing detail. Note cut spikes. Located between Camps No.1 and No.2.

MAR 1 1978

DEC 12 1978



6. Camp No.2 Building No.5,  
view looking north  
at entrance.

DEC 12 1978

MAR 1 1978



7. Flume remains showing construction detail, trough looking upstream. Located between Camps No.2 and No.3.

DEC 12 1978

MAR 1 1978



8. Flume remains showing  
construction detail of trough.  
Located between Camps No.2  
and No.3.

DEC 12 1978

MAR 1 1978





9. Flume remains showing  
construction detail of trough.  
View of same area as Fig.7  
looking east. Located  
between Camps No.2 and No.3.

DEC 12 1978

MAR 1 1978



10. Cut No.1 looking east and  
up drainage.

DEC 12 1978

MAR 1 1978



DEC 12 1978

11. Structure located between Cuts No.2 and No. 3 looking north at west half. This may have been a loading platform.

MAR 1 1978