



Photograph #1 Bissell Tavern  
Windsor, Ct. Oct. 1984  
Photot - Gail Nettles/Neg. on  
file Connecticut Historical Comm  
Facade - west exposure





Photograph #2 Bissell Tavern  
Windsor, Ct. Oct. 1984  
Photo- Gail Nettles/Neg. on file  
Connecticut Historical Comm.  
Side - south exposure



Photograph # 3 Bissell Tavern  
Windsor, Ct. Oct. 1984  
Photo - Gail Nettles/ Neg. on file  
Connecticut Historical Comm.  
Side - North exposure



2600 FORD

720 E

Photograph #4 Bissell Tavern  
Windsor, Ct. Oct. 1984  
Photo - Gail Nettles/ Neg. on file  
Connecticut Historical Comm.  
Rear - east exposure





Photograph # 5 Bissell Tavern  
Windsor, Ct. Oct. 1984  
Photo - Gail Nettles/Neg. on file  
Connecticut Historical Comm.  
North east corner showing original  
clapboards under asbestos siding



Photograph #6 Bissell Tavern  
Windsor, Ct. Oct. 1984  
Photo - Gail Nettles/Neg. on file  
Connecticut Historical Comm.  
East side (rear) showing rubble  
stone foundation





Photograph # 7 Bissell Tavern  
Windsor, Ct. Oct. 1984  
Photo - Gail Nettles/Neg. on file  
Connecticut Historical Comm.  
Entrance hall and stairs



Photograph# 8 Bissell Tavern  
Windsor, Ct. Oct. 1984  
Photo - Gail Nettles/Neg. on file  
Connecticut Historical Comm.  
Fireplace in northwest room -  
front, first floor





Photograph # 9 Bissell Tavern  
Windsor, Ct. Oct. 1984  
Photo - Gail Nettles/Neg. on file  
Connecticut Historical Comm.  
Oven in attached kitchen ell



Photograph # 10 Bissell Tavern  
Windsor, Ct. Oct. 1984  
Photo - Gail Nettles/Neg. on file  
Connecticut Historical Comm.  
South west room, second floor  
(Note wide plank flooring, corner  
post, etc.)





Photograph # 11 Bissell Tavern  
Windsor, Ct. Oct. 1984  
Photo - Gail Nettles/Neg. on file  
Connecticut Historical Comm.  
Attic south aide



Photograph #12 Bissell Tavern  
Windsor, Ct. Oct. 1984  
Photo- Gail Nettles/Neg on file  
Connecticut Historical Commission  
Attic rafters at hip ridge





Photograph # 13 Bissell Tavern  
Windsor, Ct. Oct. 1984

Photo- Gail Nettles/Neg on file

Connecticut Historical Commission  
Cellar foundation under main part of  
house; stairs from kitchen ell  
upper right.