

COMMUNITY UNITED METHODIST CHURCH

WILLIAMS, ARIZONA

HISTORIC PHOTO (COPY)

C.1923



1. United Methodist Church-SANCTUARY 2. Williams, Arizona 3. Photo by: Mike Benham 4. Photo date: April 1983 5. Negative at: Bess Grumley, Williams Arizona-86046 6. View looking southeast (1938 ADDITION ON REAR) 7. Photo 1 of 9



- 1. United Methodist Church 2. Williams, Arizona 3. Photo by : Mike Benham 4. Photo date: April 1983 5. Negative at :Bess Grumley, William s Arizona-86046
- 6. Church--looking south at sanctuary and Photo: 2 Of 9



- 1. United Methodist Church 2. Williams, Arizona 3. Photo by: Mike Benham 4. Photo date: April 1983 5. Negative at: Bess grumley Williams, Az--86046 6. Back of Church, looking north, Showing REAR OF NURSERY (L), 1923 ADDITION (M) 7. Photo 3 Of 9
 - AND W. SIDE OF COMMUNITY HALL (R)



1. Methodist Church(United) - SANCTHARY 2. Williams, Arizona 3. Photo by: Mike Benham 4. Photo date: April 1983 5. Negative at: Bess Grumley Williams, Ariz. - 86046 6.West dide of church, looking east 7. Photo 4 of 9



1. United Methodist Church-SANCTUARY 2. Williams, Arizona 3. Photo by: Mike Benham 4. Photo date: April 1983 5. Negative at: Bess Grumley Williams, Az--86046 6. North side of church, looking south, 7. Photo 5 Of 9 QUATREFOLL WINDOW PETAIL



1. United Methodist Church parsonage 2. Williams, Arizona 3. Photo by: Mike Benham 4: Photo date: April 1983 5. Negative at: Bess Grumley Williams, Ariz.-86046 6. Front of parsonage--looking east 7. Photo 6 0f 9



1. United Methodist Church-parsonage 2. Williams. Arizona 3. Photo by: Mike Benham 4. Photo date: April 1983 5. Negative at: Bess Grumley Williams. Ariz.--86046 61 Side of parsonage-looking southwest 7. Photo: 7 of 9



1. United Methodist Church-parsonage 2. Williams, Arizona 3. Photo by: Mike Benham 4. Photo date: April 1983 5. Negative at: Bess Grumley Williams. Ariz.-86046 6. Back of parsonage, looking north 7. Photo 8 of 9



1. United Methodist Church-community 2. Williams, Arizona 3. Photo by: Mike Benham 4; Photo date: April 1983 5: Negative at: Bess Grumley Williams, Ariz. -86046 6. East side, looking west 7. Photo 9 of 9