



Dallam-Merritt House, 2355 Washington St.
San Francisco, CA
photograph Anne Bloomfield, June 1983
negative with photographer
overall view: north facade from north
side of Washington Street, garage
at left rear.



Dallam-Merritt House 2355 Washington St. 2
San Francisco, CA

photo Anne Bloomfield, 28 June 1983

negative with photographer


Detail: portico and front door



Dallam-Merritt House *2355 Washington St.*³
San Francisco, CA

photo Anne Bloomfield, 28 June 1983
negative with photographer

Detail: roof profiles at southeast
corner (rear), taken from stair-
case to third floor at rear.



Dallam-Merritt House, 2355 Washington St. 4
San Francisco, CA

photo Eadweard Muybridge, 1877, en-
larged detail of panorama panel #8
of 11--negative & reproduction
California Historical Society


Roof of the house from above rear,
seen from atop Nob Hill; foreground
is Sutter St., at right Mason, mid-
left is 1st Congregational Church
at Post & Mason.

4 of 11

File: SF-General Views - 1877 - Muybridge
Panorama
Panel #8 of 11 panels (cropped)

This print may not be used without
written permission from the California
Historical Society Library, 2099 Pacific,
San Francisco, CA. 94109

neg no 22681



Dallam-Merritt House, 2355 Washington St. 5
San Francisco, CA

photo Anne Bloomfield, 28 June 1983

negative with photographer

Roof of the house from above rear,
seen from rear top floor of Pacific
Medical Center Annex on next street:
shows also rear additions, roof
deck and staircase to 3rd floor.

5 of 11



Dallam-Merritt House, 2355 Washington St. 6
San Francisco, CA

photo Anne Bloomfield, 28 June 1983

negative with photographer

Detail: east facade from driveway:

relation of 1st (right) and 2nd side
bays, with different levels of cor-
nices & hint of original wall return

6 of 11



Dallam-Merritt House, 2355 Washington St.7
San Francisco, CA
photo Anne Bloomfield, 28 June 1983
negative with photographer

Detail: east facade from outside
rear staircase: relation of (left
to right) 2nd addition, 1st addi-
tion, 2nd side bay.

7 of 11



Dallam-Merritt House, 2355 Washington St. 8

San Francisco, CA

photo Anne Bloomfield, 28 June 1983

negative with photographer

Detail: 2nd floor of 2nd addition:

interior moldings of rear bay
through ^{east} window from staircase
to 3rd floor



Dallam-Merritt House, 2355 Washington St. 9
San Francisco, CA


photo Anne Bloomfield, 28 June 1983

negative with photographer

Detail: west side with basement ball-
room entry, from steps of house
next door.



Dallam-Merritt House, 2355 Washington St. 10
San Francisco, CA
photo Anne Bloomfield, 28 June 1983
negative with photographer
Detail: rear (south) facade.



Dallam-Merritt House, ²³⁵⁵ Washington St. 11
San Francisco, CA

photo Anne Bloomfield, 28 June 1983
negative with photographer

Detail: east facade from garage:
staircase to third floor, basement
areaway, Washington Street in
background.