



Woods-Crook-Tredaway House

Jacksonville, Alabama, Calhoun County

Hammett Photography, November 1985

Alabama Historical Commission

Northwest Elevation

Photo number: 1



Woods-Crook-Tredaway House

Jacksonville, Alabama, Calhoun County

Hammett Photography, November 1985

Alabama Historical Commission

Southwest Elevation

Photo number: 2



Woods-Crook-Tredaway House

Jacksonville, Alabama, Calhoun County

Hammett Photography, November 1985

Alabama Historical Commission

Northeast Elevation

Photo number: 3



Woods-Crook-Tredaway House  
Jacksonville, Alabama, Calhoun County

Hammett Photography, November 1985  
Alabama Historical Commission

Southeast elevation

Photo number: 4





Woods-Crook-Tredaway House

Jacksonville, Alabama, Calhoun County

Hammett Photography, November 1985

Alabama Historical Commission

Foyer

Photo number: 5



Woods-Crook-Tredaway House

Jacksonville, Alabama, Calhoun County

Hammett Photography, December 14, 1985

Alabama Historical Commission

Windows and woodwork in south parlor downstairs

Photo number: 6



Woods-Crook-Tredaway House  
Jacksonville, Alabama, Calhoun County

Hammett Photography, December 14, 1985  
Alabama Historical Commission

Window and woodwork in downstairs bedroom 1  
adjoining south parlor

Photo number: 7



Woods-Crook-Tredaway House

Jacksonville, Alabama, Calhoun County

Hammett Photography, December 14, 1985

Alabama Historical Commission

Mantel and woodwork in downstairs bedroom 1  
adjoining south parlor

Photo number: 8





Woods-Crook-Tredaway House  
Jacksonville, Alabama, Calhoun County

Hammett Photography, December 14, 1985  
Alabama Historical Commission

Mantel and woodwork in south bedroom 2

Photo number: 9



Woods-Crook-Tredaway House

Jacksonville, Alabama, Calhoun County

Hammett Photography, December 14, 1985

Alabama Historical Commission

Italian green marble mantel located in north  
parlor downstairs

Photo number: 10



Woods-Crook-Tredaway House  
Jacksonville, Alabama, Calhoun County

Hammett Photography, December 14, 1985  
Alabama Historical Commission

Front main entrance downstairs

Photo number: 11



Woods-Crook-Tredaway House  
Jacksonville, Alabama, Calhoun County

Hammett Photography, December 14, 1985  
Alabama Historical Commission

Wood mantel in northwest front room upstairs

Photo number: 12





Woods-Crook-Tredaway House  
Jacksonville, Alabama, Calhoun County

Hammett Photography, December 14, 1985  
Alabama Historical Commission

Woodwork and typical door downstairs  
bedroom 2

Photo number: 13



Woods-Crook-Tredaway House

Jacksonville, Alabama, Calhoun County

Hammett Photography, December 14, 1985

Alabama Historical Commission

Old milk house later converted to cottage  
about 1938

Photo number: 14



Woods-Crook-Tredaway House

Jacksonville, Alabama, Calhoun County

Hammett Photography, December 14, 1985

Alabama Historical Commission

Old carriage house, later used as smoke house,  
reduced to one story and presently used as garage  
and storage house

Photo number: 15