



Photo #1 of 10

Oak Ballroom (CX06-3)  
Schuyler, Colfax County, Nebraska

Photo by D. Murphy, Nebraska State  
Historical Society  
March, 1980 (NSHS 8003/7:6)

General view looking west toward the  
city park showing the ballroom in the  
left background.





Photo #2 of 10

Oak Ballroom (CX06-3)  
Schuyler, Colfax County, Nebraska

Photo by D. Murphy, Nebraska State  
Historical Society  
March, 1980 (NSHS 8003/7:9)

View looking northwest showing the  
southeast facade.





Photo #3 of 10

Oak Ballroom (CX06-3)  
Schuyler, Colfax County, Nebraska

Photo by D. Murphy, Nebraska State  
Historical Society  
March, 1980 (NSHS 8003/7:11)

View looking northwest showing detail  
of the front (southeast) entry.

29





Photo #4 of 10

Oak Ballroom (CX06-3)  
Schuyler, Colfax County, Nebraska

Photo by D. Murphy, Nebraska State  
Historical Society  
March, 1980 (NSHS 8003/7:35)

View looking north showing the southeast  
and southwest facades.





Photo #5 of 10

Oak Ballroom (CX06-3)  
Schuyler, Colfax County, Nebraska

Photo by D. Murphy, Nebraska State  
Historical Society  
March, 1980 (NSHS 8003/7:31)

View looking southeast showing the  
northwest facade.





Photo #6 of 10

Oak Ballroom (CX06-3)  
Schuyler, Colfax County, Nebraska

Photo by D. Murphy, Nebraska State  
Historical Society  
March, 1980 (NSHS 8003/8:32a)

Interior view looking northeast across  
the dance floor toward the fireplace.





Photo #7 of 10

Oak Ballroom (CX06-3)  
Schuyler, Colfax County, Nebraska

Photo by D. Murphy, Nebraska State  
Historical Society

March, 1980 (NSHS 8003/9:11)

Interior view looking south showing  
the bandshell and stage area.





Photo #8 of 10

Oak Ballroom (CX06-3)  
Schuyler, Colfax County, Nebraska

Photo by D. Murphy, Nebraska State  
Historical Society  
March, 1980 (NSHS 8003/8:34a)

Interior view showing detail of oak  
pedestal table.





Photo #9 of 10

Oak Ballroom (CX06-3)  
Schuyler, Colfax County, Nebraska

Photo by D. Murphy, Nebraska State  
Historical Society  
March, 1980 (NSHS 8003/9:5)

Interior view looking west across the  
dance floor toward the bar and lunch room.

9





Photo #10 of 10

Oak Ballroom (CX06-3)  
Schuyler, Colfax County, Nebraska

Photo by D. Murphy, Nebraska State  
Historical Society  
March, 1980 (NSHS 8003/9:9)

Interior view looking south showing  
the bar area.