



Looking North on and from downtown Corvallis, Oregon

*Heinrich
1938-39*

Corvallis Hotel
201-211 SW Second Street
Corvallis, Benton County, Oregon

1 of 8 Historic view, 1929
Looking north on Second Street
Hotel Corvallis on right, Oregon
State Univeristy Archives Photo
P 176:355



Corvallis Hotel
201-211 SW Second Street
Corvallis, Benton County, Oregon

2 of 8

North and west elevations from
intersection of Second and Madison.

Lucille Tisdale Photo, 1987
Benton County Historical Museum
PO Box 47
Philomath OR 97397



Corvallis Hotel
201-211 SW Second Street
Corvallis, Benton County, Oregon

3 of 8
North (SW Madison Avenue) facade.

Lucille Tisdale Photo, 1987
Benton County Historical Museum
PO Box 47
Philomath OR 97397



MEMORIES

Wilbur Christ's
FINE JEWELRY

LOBBY PARKS

LOBBY PARKS

Corvallis Hotel
201-211 SW Second Street
Corvallis, Benton County, Oregon

4 of 8
West (SW Second Street) facade.

Lucille Tisdale Photo, 1987
Benton County Historical Museum
PO Box 47
Philomath OR 97397



Corvallis Hotel
201-211 SW Second Street
Corvallis, Benton County, Oregon

5 of 8

Detail of frieze decorated in
simulated pargetry, west facade.

Lucille Tisdale Photo, 1987
Benton County Historical Museum
PO Box 47
Philomath OR 97397



EXIT

DOOR LOCKED
ON 8th FLOOR
ROOM 801
8000 1st AVE
8000 1st AVE

Corvallis Hotel
201-211 SW Second Street
Corvallis, Benton County, Oregon

6 of 8

Coved and coffered ceiling
detail, lobby interior.

Lucille Tisdale Photo, 1987
Benton County Historical Museum
PO Box 47
Philomath OR 97397



TELEPHONE

Corvallis Hotel
201-211 SW Second Street
Corvallis, Benton County, Oregon

7 of 8
Lobby staircase, looking north.

Lucille Tisdale Photo, 1987
Benton County Historical Museum
PO Box 47
Philomath OR 97397



Corvallis Hotel
201-211 SW Second Street
Corvallis, Benton County, Oregon

8 cf 8
Typical guest room sink.

Lucille Tisdale Photo, 1987
Benton County Historical Museum
PO Box 47
Philomath OR 97397