

Photo credit: R. R. Lutz
Date of photo: circa 1920
Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

View from southeast soon after hotel was opened.

Photo 1 of 14



Photo credit: Bonnie J. Halda
Date of photo: February 7, 1983
Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

View from southeast.

Photo 2 of 14



Photo credit: Bonnie J. Halda
Date of photo: February 7, 1983
Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

View from southwest.

Photo 3 of 14



Photo credit: Bonnie J. Halda
Date of photo: February 7, 1983
Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

East facade, view from southeast.

Photo 4 of 14




Photo credit: Bonnie J. Halda
Date of photo: February 7, 1983
Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

Detail of first-floor terra-cotta panels on south facade.

Photo 5 of 14



Photo credit: Bonnie J. Halda
Date of photo: February 7, 1983
Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

Lobby, view from northwest.

Photo 6 of 14



Photo credit: Bonnie J. Halda Date of photo: February 7, 1983

Location of negative: State Historical Society of North Dakota North Dakota Heritage Center

Bismarck, ND 53505

Lobby, view from entry on the south, looking towards dining room.

Photo 7 of 14



Photo credit: Bonnie J. Halda
Date of photo: February 7, 1983
Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

Lobby, detail of stairway in northeast corner.

Photo 8 of 14




Photo credit: Bonnie J. Halda Date of photo: February 7, 1983 Location of negative: State Historical Society of North Dakota North Dakota Heritage Center Bismarck, ND 58505

Dining room, view from southeast.

Photo 9 of 14



Photo credit: Bonnie J. Halda Date of photo: February 7, 1983 Location of negative: State Historical Society of North Dakota North Dakota Heritage Center Bismarck, ND 58505

Cafe seating area (former portion of lobby), view from north.

Photo 10 of 14



Photo credit: Bonnie J. Halda
Date of photo: February 7, 1983
Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

Fourth floor hall, view from south.

Photo 11 of 14



Photo credit: Bonnie J. Halda
Date of photo: February 7, 1983
Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

Room 233 on second floor, view from southwest.

Photo 12 of 14



Photo credit: Bonnie J. Halda
Date of photo: February 7, 1983
Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 53505

Typical room on fourth floor

Photo 13 of 14



Photo credit: Bonnie J. Halda
Date of photo: February 7, 1983
Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

Hall in former bank lobby, view from north towards entry.

Photo 14 of 14