

Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Chelsea Village and the First Branch Valley; View Northeast Photograph 1 82-77-271



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: View North on Vermont Route 110, South end of District Photograph 2

82-7-305



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: #'s 11, 10, 9, 7, 6; View North on Vermont Route 110 Photograph 3

7 4,



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: #'s 12, 13, 14, 15; View North on Vermont Route 110 Photograph 4

827304



82-A-304

Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: #'s 24, 25, 26; View North on Vermont Route 110 Photograph 5



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Orange County Courthouse, #38; View East, the South Common Photograph 6

82-7-272



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: #'s 63, 64, 65, 66; View Northeast at the corner of Vermont Route 110 and South Bank Street Photograph 7




824308

Cheisea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: View West, Jail Brook Photograph 8



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: #'s 50, 48, 47; View East, the North side of Vermont Route 115 Photograph 9 82-A-306



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: #'s 43, 42, 41, 61, 71, 72, 50, 48, 47; View East, Vermont Route 115 Photograph 10

82-9-286




Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date:: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: #'s 53, 52, 51; View East, the North Common Photograph 11




824280

Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: #'s 63, 70, 71, 72, 57, 60; View West, the North Common Photograph 12



82-7-304

Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: #'s 71, 72, 57, 88, 89, 90; View North, Vermont Route 110 Photograph 13




Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: #'s 74, 81, 83, 84, 85; View West, Maple Avenue Photograph 14


82-7-307



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: #'s 83, 84, 85, 51, 77; View East, Maple Avenue and the North Common Photograph 15



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: #'s 98, 99, 100, 115; View North, Vermont Route 110 Photograph 16



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: #'s 114, 115, 116, 117, 118, 120, 121, 122; View North, the East side of Vermont Route 110 Photograph 17 82A-309

-



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Vermont Route 110 and the bridge over South Washington Brook; View North Photograph 18

82-A-305



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: #'s 110, 111, 112, 113; View Northeast, the North side of Vermont Route 100 Photograph 19




Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: #'s 117, 118, 120, 121; View

South, the East side of Vermont Route 110 and the bridge over South Washington Brook Photograph 20

82-8369



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: #'s 130, 132, 133, 134, 135, 136, 138, 140, 142, 144, 60; View Northeast, the East side of Vermont Route 110 Photograph 21 82-7-271




Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: #3, 2, 1, Heath House and Barns; View Northeast Photograh 22

83-7-74



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Heath House, #3; View East Photograph 23



82-7-271

Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Luce House, #4; View East Photograph 24



82-7-271

Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Sons of Union Veteran's Hall-Allen House, #5; View East Photograph 25



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Graf House, #7; View Northeast Photograph 26

82-7-271



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Allen House, #9; View Northeast Photograph 27



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: McCullough House, #11; McCullough House, #10; View Northeast Photograph 28



82-A-304

Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Metz House, #14; View Northwest Photograph 29



82A304

Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Kennedy House, #15; McCullough House, #16; View Northwest Photograph 30



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Norton-Titus House, #19; View Northeast Photograph 31

824271



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Keeper House, #23; McFarlane House, #22; View Northeast Photograph 32




83-A-74

Chelsea Village Historic District Chelsea, Vermont Credit: Gina Campoli Date: May, 1983 Negative Filed at Vermont Division for Historic Preservation Description: Keyser Outbuilding, #23B; Forbes Barn, #29A; View East Photograph 33




Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Lamb-Davis-Tuckett House-Shire Inn, #25; View West Photograph 34 82-7-279



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Blake-Clark-Jackson House, #26; View Northwest Photograph 35

827279



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Blake-Clark-Jackson House, #26; View West Photograph 36



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Rufus Hyde House-Parkview-Field's Office and Residence, #27; View West Photograph 37

827279



82-7-279

Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Royce House, #28; View West Photograph 38



Chelsea Village Historic District Chelsea, Vermont Credit: Gina Campoli Date: May, 1983 Negative Filed at Vermont Division for Historic Preservation Description: Royce Barn, #28A; View West Photograph 39

83-4-74



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Hale-Hall-Waterman-Forbes House, #29; View East Photograph 40



82-A-308

Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Chelsea School, #30; View South Photograph 41



82-7-292

Chelsea Village Historic District Chelsea, Vermont Credit: Courtney "Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Benedict House, #31; View Northeast Photograph 42



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Pratt House, #32; View Southwest Photograph 43

82-A-308



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Hatch House, #34; View East Photograph 44



82-7308

Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Farr House, #36; Coburn House, #35; View Northwest Photograph 45



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Rein House, #37; View Northwest Photograph 46

-

82-A-308



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Orange County Courthouse, #38; .View East Photograph 47

82-7-291



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Hale-Brodne House, #39; View East Photograph 48



824-280

Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Kezer House, #40; View South Photograph 49



82-7-280

Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Hutchinson House, #41; View Southwest Photograph 50




Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Santamore House, #42; View Southwest Photograph 51

82-7-280



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Ladd House, #43; View Southwest Photograph 52





Chelsea Village Historic District Chelsea, Vermont Credit: Gina Campoli Date: May, 1983 Negative Filed at Vermont Division for Historic Preservation Description: Thody Barn, #46; View Northeast Photograph 53



82A-280

Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Thody House, #48; View North Photograph 54



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Congregational Church-United Church of Chelsea, #51; View Northeast Photograph 55

82A271



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Stearns-Velas-Bixby-Richter House, #53; View Northeast Photograph 56




82A-286

Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Beckwith-Hatch House, #55; Congregational Parsonage, #54; View North Photograph 57



82-9-280

Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Ackerman's Store, #57; Dana-Hayward House, #56; View Northwest Photograph 58



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Chelsea Town Hall and Library, #60; View Northeast Photograph 59

82-A-306



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Mattoon-Button House, #61; Gill House, #62; View East Photograph 60



82A-292

Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Bacon and Hall Block-Proctor Bank, #63; View Northeast Photograph 61



82-7-308

•

Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Tracey-Roberts House, #65; View South Photograph 62



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: McIntosh House, #66; View Northwest Photograph 63

82-A-308



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: McIntosh Barn, #67; Button Shed, #68; View Northwest Photograph 64




82A279

Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Chelsea Country Store, #71; Old Hood Store, #72; View Northwest Photograph 65



8272-280

Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Hayward House, #75; View South Photograph 66



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Kennedy House, #76; View Southwest Photograph 67

82-A-280




Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Mize House, #77; Mize Barn, #77A; View Southeast Photograph 68



83-7-74

Chelsea Village Historic District Chelsea, Vermont Credit: Gina Campoli Date: May, 1983 Negative Filed at Vermont Division for Historic Preservation Description: Atwood-Button House, #79; View Southwest Photograph 69



82A-279

Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Comeford House, #80; View North Photograph 70




Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Dodge-Bacon-Atwood-Morss House, #81; View West Photograph 71

82-A-279



Chelsea Village Historic District Chelsea, Vermont Credit: Gina Campoli Date: May, 1983 Negative Filed at Vermont Division for Historic Preservation Description: Dodge-Bacon-Atwood-Morss House Door Detail, #81; View West Photograph 72





Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Morss Barn, #81A; View North Photograph 73



8277279

Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Babcock House, #83; View Northwest Photograph 74



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Button House, #84; View Northwest Photograph 75

82A-209




Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Preston Cottages, #86A, #86B; View Northwest Photograph 76



82-A-307


Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Chelsea Village Spinner, #88; Chelsea Restaurant, #89; View West Photograph 77



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Watson House, #90; View Northwest Photograph 78 824305



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Boardman House, #91; Godfrey House-Chelsea Home for the Aged, #92; View Northwest Photograph 79 82-7-307



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Colby House, #94; View Northwest Photograph 80



8277307

Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Chelsea Mills, #95; View West Photograph 81



82-7367

Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Hood-Helmer House, #96; Chelsea Fire Station-Dickinson Barn, #97; View West Photograph:82



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Dickinson House, #98; View Northwest Photograph 83

82-A307



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Royce House, #99; View West Photograph 84



82-A-367

Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Hayward House, #100; View Northwest Photograph 85



Chelsea Village Historic District Chelsea, Vermont Credit: Gina Campoli Date: May, 1983 Negative Filed at Vermont Division for Historic Preservation Description: Parker House, #103; View Northwest Photograph 86

83-77-74



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Dearborn-Cahill House, #104; View Northwest Photograph 877



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Hood-Davis House-Brook Haven Home for Boys, #105; View West Photograph 88

27307



82-A-308

Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Reed House, #106; View Northwest Photograph 89



82-7-308

Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Anderson House, #107; View West Photograph 90



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Watson-Jones House, #109; View West Photograph 91



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Sanborn House, #110; View Cort Northeast Photograph 92

82-A-309



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Martin House, #111; View East Photograph 94


82-A309



82-9-305

Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Martin House, #111; View North Photograph 93

10



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Chelsea Health Center Barn, #114; Buck-Comstock House-Chelsea Health Center, #115; View North Photograph 95




82-7-305

Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Godfrey-Wilson-Preston Farm, #116; View Northeast Photograph 96



827309

Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Kelman-Rich House, #118; View Northeast Photograph 97



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Rogers House, #120; View East Photograph 98

82 A-309



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Dickinson-Lipman House, #123; View East Photograph 99



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Sanborn House, #124; View Northeast Photograph 100

82-7-309



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Hatch-Lewis House-Chelsea Historical Society, #126; View Northeast Photograph 101 827309



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Hatch-Ingersoll House, #127; View Northeast Photograph 102

82-7309



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Sanborn House, #129; View Northeast Photograph 103



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: American House-Young House, #130; Tinker Manufacturing Company-Smith-Colby House, #132; View Northeast Photograph 104

82-7-306



82-A-306

Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Tucker-Blum House, #133; Downing House, #134; View Northeast Photograph 105



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Gates-Corwin-Brooks House, #135; View Northeast Photograph 106

82-17-306



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Gates-Corwin-Brooks House Door Detail, #135; View East Photograph 107

1 .

.



82-7-306

Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Chelsea Market-Hobbs-Berry-Sanborn Harness Shop-Brooks Property, #136; Button House, #138; Button Barn, #139; View Northeast Photograph 108



82-7-272

Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Button House, #140; Old Orange County Bank-Van Dyk Property, #142; View Northeast Photograph 109



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation Description: Old Orange County Bank-Van Dyk Property, #142; George Washington Lodge, #144; View East Photograph 110

82-7306



Chelsea Village Historic District Chelsea, Vermont Credit: Courtney Fisher Date: November, 1982 Negative Filed at Vermont Division for Historic Preservation

Description: Button Barn, #141; Boardway and Cilley Property, #143; Bohanon-Hyde-Townsend House-E. Cilley Funeral Home, #59; View North Photograph 111