



Moquin's Bakery

78 Rose St; Chittenden County, Vermont

Credit: Liz Pritchett

August 1995

Negative on file at Vermont Div. for Historic Preservation  
Context Photo, view looking southeast on Rose St.

Photograph 1



Moquin's Bakery

78 Rose St, Chittenden County, Vermont

Credit: Liz Pritchett August 1995

Neg. on file at Vermont Div. for Historic Preservation

View looking northeast of west facade

Photo 2





Moquin's Bakery

78 Rose St Clarendon Co., Vermont

Wiz Pritchett, August 1995

Neg. on file at Vermont Div. for Historic Preservation

View looking east of front facade

Photo 3.





Moquin's Bakery

78 Rose St Clarendon Co, Vermont

Credit: Liz Pritchett August 1995

Neg. on file at Vermont Div. for Historic Preservation

View looking east of south end of front facade with garage bay

Photo 4.





Moquin's Bakery

78 Rose St Chittenden Co. Vermont

Credit: Liz Pritchett August 1995

Dep. on file at Vermont Div. for Historic Preservation

View looking southeast of north (left), west (right) facades

Photo 5







Moquin's Bakery

78 Reese St Chittenden Co Vermont

Credit: Liz Pitelnet August 1995

Neg on file at Vermont Div. for Historic Preservation

View looking southeast of rear corner; east (left) +  
north (right) facades.

Photo 6



Moquin's Bakery

78 Rose St Clarendon Co. UT

Credit: Liz Pitchett August 1995

Log on file at Vermont Div. for Historic Preservation  
View looking west of south facade.

Photo 7.





ACME  
PAINT & GLASS

6581400 • BURLINGTON

ACME  
PAINT & GLASS  
BURLINGTON

NO  
TRESPASSING

NOTICE  
Z

Moquin's Bakery

78 Rose St Clarendon Co, Vermont


Credit: Liz Pitchett

August 1995

Neg. on file at Vermont Div. for History & Preservation

View of main entrance

Photo 8





Moquin's Bakery

78 Rose St Chittenden Co, Vermont

Credit: Liz Pritchard

August 1995 Negative at Vermont Division for Historic

View of detail of front window c1945 appendage <sup>Preservation</sup>

Photo 9



Moquin's Bakery

78 Rose St Chittenden Co, Vermont

Credit: Liz Pritchett

August 1995

Neg on file at Vermont Div. for Historic Preservation

View of interior: painted recipe panel in mixing room.

Prob 10.