84000331-

United States Department of the Interior National Park Service For NPS use only **National Register of Historic Places** received OCT NOV 1984 1984 Inventory—Nomination Form date entered See instructions in How to Complete National Register Forms Name "Sunnvcroft" Location N/A not for publication Locust Hill N/A_ vicinity of city, town Limerick, Maine 23 code York county code Classification 3. Category Ownership Status **Present Use** _ district _ public _X__ occupied ___ agriculture museum X_building(s) _X_ private _ unoccupied _ commercial _ park ____ private residence structure _ both work in progress educational site **Public Acquisition** Accessible entertainment _ religious _ object N/A in process scientific _ yes: restricted government ____ being considered industrial X yes: unrestricted no military other: 4. **Owner of Property** name Rodney Barrett and Paul Santella street & number Locust Hill city town Timorick vicinity of state Maine 04048 York County Registry of Deeds Alfred, Maine state **Representation in Existing Surveys** 6.

title	N/A	has this property been determ	ined eligible?	? _{N/A} yes	no
date		federal	state	county	local
depository	/ for survey records				
city, town			state		

Type all entries—complete applicable sections

1.

historic and or common Moulton Place 2.

street & number

state

	Liller	LCK -		
5.	Location	of	Legal	Description

courthouse, registry of deeds, etc.

street & number

city, town

city, town

_ transportation

031

7. Description

Condition	
X excellent	deteriorated
good	ruins
fair	unexposed

Check one __X_ original site ____ moved date __

Describe the present and original (if known) physical appearance

Check one

X_unaltered

altered

Sunnycroft, a two-and-one-half story Colonial Revival style structure, is a wood frame building with clapboard siding. The house is constructed on a fieldstone foundation which, on the east side, is exposed to create an additional above-ground story. There is a large columned portico on the south facade and a smaller one over the main entrance, plus a porte-cochere on the east side. The placement of these two porticos, in addition to several onestory wings and the existence of a variety of different sized windows, contribute to a picturesque asymmetry in the exterior design.

The Colonial Revival style trim of the building includes fluted Ionic columns, a cornice with modillion blocks and a large Palladian staircase window. The use of semi-circular and oval windows also contribute to the building's Colonial styling. There is also a balustrade with urns over the entrance portico.

8. Significance

Period	Areas of Significance—C	heck and justify below		
15001599 16001699 17001799 18001899	archeology-prehistoric	conservation	Iandscape architectur Iaw Iterature Iterature Iterature military Iterature politics/government	e religion science sculpture social/ humanitarian theater transportation other (specify)

Specific dates	1922	Builder/Architect	Unknown	2
Statement of Signi	ficance (in one p	paragraph)	at the the Autor	() 利息公告》

Although erected in 1921-1922 in strict conformance with the requisites of a modern home, and in the Colonial Revival style, there is a dominating quality of old New England pervading "Sunnycroft", the property built by Mr. Charles G. Moulton, which is agreeably in keeping with earlier architectural traditions of the State.

The individual site of "Sunnycroft" in Limerick, is upon the summit of a picturesque slope of land, the deviations of which are followed by the various units of the house in a delightfully rambling manner.

To find a structure of such ideosyncratic charm in a small rural community serves to increase its architectural significance which, by itself is very considerable.

9. Major Bibliographical References

"Country Homes"	· .	1922,	month	unknown.
-----------------	-----	-------	-------	----------

10. G	eographical	Data			
Acreage of no Quadrangle n UTM Reference		1	_	C	Quadrangle scale 1:62500
	5 15 3 18 10 4 18 31 sting Northing	8 7 7 4 1 0	B Zon	Easting	Northing
C			┍└┈ ╒└┈ н└╵╹		
Verbal boun	dary description and ju	stification			
	Asses	sor's Map 11	l, Lot 13	•	
List all state	es and counties for pro	perties overlap	ping state o	r county bou	undaries
state		code	county		code
state		code	county	ă.	code
11. Fo	orm Prepare	ed By			· · · · · · · · · · · · · · · · · · ·
name/title	Frank A. Beard, H	listorian/Roc	jer G. Reed	, Archited	ctural Historian
organization	Maine Historic Pr	eservation (Commission	date	July, 1984
street & numb	er 55 Capitol Street	, Station #6	55	telephone	207/289-2132
city or town	Augusta,			state	Maine 04333
12. St	ate Historio	c Prese	rvatior	n Offic	er Certification
The evaluated	significance of this prope	rty within the sta	te is:		· · · · · · · · · · · · · · · · · · ·
	national	state	local		
665), I hereby according to t		set forth by the	National Regis	ter and certify	vation Act of 1966 (Public Law 89- y that it has been evaluated
title _C	5. H.P.O.	\sim	/		date 10/1/84
LA	certify that this property is) Ent	National Regis tered in th tional Regi	.0	date 11-8-84
Keeper of	the National Register	Na	v		
Attest:					date

GPO 894-788

8/29/28

United States Department of the Interior National Park Service

National Register of Historic Places Continuation Sheet

Section number _____ Page ____

Sunnycroft York County, MAINE

ADDITIONAL INFORMATION

Sor Keeper Sitting Songe 10/12/88 ____

NPS Form 10-900-a

8/29/88

United States Department of the Interior National Park Service

National Register of Historic Places Continuation Sheet

Section number _____ Page ___

"Sunnycroft" Limerick, Maine Amended Description #7; Significance #8 August 4, 1988

Kirk F. Mohney, Architectural Historian Maine Historic Preservation Commission 55 Capitol Street, Station #65 Augusta, Maine 04333

#7

Standing off of the northwest corner of the main building is the caretaker's house, a modest one-story with attic, rectangular frame dwelling sheathed in weatherboards. Like the larger house, it rests on a prominent rubble stone foundation, but it is covered by a gable roof. The entrance is located at the southwest corner behind a porch whose gabled roof and decorative entablature are supported by a pair of Tuscan columns. To the north of the entryway are a pair of widely separated two-over-two windows. The north gable end is punctuated by two windows in the attic and a door on the first story. Four windows, including a pair near the north end, are located on the east side, but only the unit at the southeast corner appears to be original. A door and window are positioned in the tall basement that is exposed here through a change in the grade. Three windows are located in the south end, two of which are in the attic. The modestly finished interior consists of two rooms and a bathroom in the first story and an open loft in the attic.

#8

The diminutive caretaker's cottage that stands behind the main dwelling is believed to have been built in 1921-22. Its physical location on the property and modest appearance (it in fact looks like utilitarian buildings of the late nineteenth century) underscore its secondary role. Nevertheless, it is significant relative to the principal dwelling by virtue of its role as a residence for the estate's staff and as an architectural manifestation of the social/economic distinction between the owner and his employees.