

Photo 1

General view looking southwest of the facade at present




Photo 2

Historic view, Mohr Block at right, from Fort Wayne Illustrated, 1897 Collection Allen County Historical Society



Photo 3

General view looking northwest of the rear walls



Photo 4

General view looking northeast of the rear walls



Photo 5

General view looking north in the former first floor display area



Photo 6

Detail view looking northwest of second floor stair and elevator landing



Photo 7

General view looking south in the former second floor display area




Photo 8

Detail view looking west of front window treatment on second floor



Photo 9

General view looking southeast of the front wall of the 1926 salon at the rear of the second floor



Photo 10

Detail view looking north of the plaster detailing in the side rooms of the 1926 salon



Photo 11

General view looking south in the third floor hallway



Photo 12

General view looking northwest in the third floor general office area



Photo 13

General view looking southeast in the rear room on the third floor