



San Geronimo Catholic Church (180),
view from southeast

San Geronimo Historic District


San Geronimo, New Mexico

Betsy Swanson, New Mexico State

Historic Preservation Bureau

July, 1980

"C"



San Geronimo Catholic Church (18),
view from northeast

San Geronimo Historic District

San Geronimo, New Mexico

Betsy Swanson, New Mexico State

Historic Preservation Bureau

April, 1980

NEG.# ~~BS~~ BS-16-19

From right to left:

24 - school - non-contributing

18 - church - contributing

5 - house - contributing

4 - house - contributing



San Geronimo Catholic Church (18),
interior view of apse
San Geronimo Historic District
San Geronimo, New Mexico
Betsy Swanson, New Mexico State
Historic Preservation Bureau
July, 1980

"C"



Men's Literary Society Club House (8)
side view from south showing Hermit
Peak in background,
San Geronimo Historic District
San Geronimo, New Mexico
Betsy Swanson, New Mexico State
Historic Preservation Bureau
April, 1980

NEG. # BS - 17 - 33

"C"



Barn (10), view from south
San Geronimo Historic District
San Geronimo, New Mexico
Betsy Swanson, New Mexico State
Historic Preservation Bureau
July, 1980

"C"



House (9), view from southwest
San Geronimo Historic District
San Geronimo, New Mexico
Betsy Swanson, New Mexico State
Historic Preservation Bureau
April, 1980

NEG. # BS 15-28

"C"



House (6), side view from north
San Geronimo Historic District
San Geronimo, New Mexico
Betsy Swanson, New Mexico State
Historic Preservation Bureau
April, 1980

NEG. # BS - 17 - 29

"C"



House (1), view from north,
San Geronimo Historic District
San Geronimo, New Mexico
Betsy Swanson, New Mexico State
Historic Preservation Bureau
April, 1980

NEG. # BS-17-20

"C"



House-store (9) and house (1) in
background. View from north.
San Geronimo Historic District
San Geronimo, New Mexico
Betsy Swanson, New Mexico State
Historic Preservation Bureau
July, 1980

"C"



Houses, (2) left and (3) right,
east facades
San Geronimo Historic District
San Geronimo, New Mexico
Betsy Swanson, New Mexico State
Historic Preservation Bureau
July, 1980

"C"



House (3), south end
San Geronimo Historic District
San Geronimo, New Mexico
Betsy Swanson, New Mexico State
Historic Preservation Bureau
April, 1980

NEG. # BS 15-4

"C"



Houses (16 (left) and (15) right,
view from south.

San Geronimo Historic District

San Geronimo, New Mexico

Betsy Swanson, New Mexico State

Historic Preservation Bureau

July, 1980

"C"



Barns (formerly houses) (20 & 21)
view from south
San Geronimo Historic District
San Geronimo, New Mexico
Betsy Swanson, New Mexico State
Historic Preservation Bureau
April, 1980

NEG. # 135-17-17

"C"



Barns, (10) right, (11) left,
(20) background, view from north,
San Geronimo Historic District
San Geronimo, New Mexico
Betsy Swanson, New Mexico State
Historic Preservation Bureau
July, 1980

"C"



Barn (10), view from west
San Geronimo Historic District
San Geronimo, New Mexico
Betsy Swanson, New Mexico State
Historic Preservation Bureau
July, 1980

"C"



San Geronimo Historic District
view from northeast
San Geronimo, New Mexico
Betsy Swanson, New Mexico State
Historic Preservation Bureau
July, 1980

From right to left:

- 17 - house - contributing
 - 8 - club house - contributing
 - 24 - school - non-contributing
 - 18 - church - contributing
 - 5 - house - contributing
 - 4 - house - contributing
 - 9 - house - contributing
 - 26 - house - non-contributing
 - 25 - house - non-contributing
 - 10 - barn - contributing
-
- 20 - barn - contributing
 - 21 - barn - contributing
 - 1 - house - contributing



San Geronimo Historic District
view from south
San Geronimo, New Mexico
Betsy Swanson, New Mexico State
Historic Preservation Bureau
April, 1980

NEG.# BS-14-29

From right to left:

- 26 - house - non-contributing
- 9 - house - contributing
- 18 - church - contributing
- 21 & 20 - barns - contributing (foreground)
- 16 - house - contributing (background)
- 25 - house - non-contributing
- 1 - house - contributing



San Geronimo Historic District

view from east

San Geronimo, New Mexico

Betsy Swanson, New Mexico State

Historic Preservation Bureau

July, 1980



House-store (9) and San Geronimo
Catholic Church (18), view from south
San Geronimo Historic District
San Geronimo, New Mexico
Betsy Swanson, New Mexico State
Historic Preservation Bureau
July, 1980

11C "



House-store (9), pressed tin ceiling
of room apparently used for commer-
cial purpose,
San Geronimo Historic District
San Geronimo, New Mexico
Betsy Swanson, New Mexico State
Historic Preservation Bureau
April, 1980

NEG. # B5-15-35

"C"



San Geronimo Catholic Church (18)
and house (9), view from south
San Geronimo Historic District
San Geronimo, New Mexico
Betsy Swanson, New Mexico State
Historic Preservation Bureau
April, 1980

NEG. # BS-17-19

"C"



Houses, left to right (4), (6, top
of hill), (3) and (2), viewed from
south on Forest Route 18.
San Geronimo Historic District
San Geronimo, New Mexico
Betsy Swanson, New Mexico State
Historic Preservation Bureau
July, 1980



San Geronimo Historic District
view from Forest Route 18 to south,
in foreground house (1) rear view,
beyond two barns (former houses)
(20 & 21), recent house (25), Church
(18) and house (9) to right of church
San Geronimo, New Mexico
Betsy Swanson, New Mexico State
Historic Preservation Bureau
July, 1980

From right to left:

- 1 - house - contributing
- 21 - barn - contributing
- 20 - barn - contributing
- 26 - house - non-contributing (behind #20)
- 9 - house - contributing
- 25 - house - non-contributing
- 18 - church - contributing



House (3), east facade entrance,
San Geronimo Historic District
San Geronimo, New Mexico
Betsy Swanson, New Mexico State
Historic Preservation Bureau
April, 1980

NEG. # BS-17-21

"1/2"