



AUG 24 1978

Name: GOLDEN MINE ~~FARM~~

Location: Near Milford, Delaware <sup>Kent County</sup>

Photographer: Thomas Draper

Date: 1969

Location of Negative: Division of Hist. & Cult.

Affairs, Bureau of Archaeology & Historic Preservation,  
Hall of Records, Dover, De.

Description: View of the facade.

Photograph Number: K- 171 (#1) 87

NOV 29 1977



AUG 24 1978

Name: GOLDEN MINE ~~FARM~~

Location: Near Milford, Delaware <sup>KEAT COUNTY</sup>

Photographer: James Kimmey

Date: 1969

Location of Negative: DHCA: B/A&HP: Hall of Records, Dover

Description: View of the winding staircase. (Mrs. Robert Kennedy, Sr., Lewes, DE)

Photograph Number: K-171 (#2) 87

NOV 29 1977



AUG 24 1978

Name: GOLDEN MINE FARM

Location: Near Milford, <sup>Kent County</sup> Delaware

Photographer: James Kimmey

Date: 1969

Location of Negative: DHCA: B/A&HP: Hall of Records, Dover.  
(Mrs. Robert Kennedy, Sr., Lewes, DE)

Description: View of the fireplace in the living room.

Photograph Number: K-171 (#3) 87 NOV 29 1977



AUG 24 1978

Name: GOLDEN MINE ~~FARM~~

Location: <sup>KENT COUNTY</sup>  
Near Milford, Delaware

Photographer: James Kimmey

Date: 1969

Location of Negative: DHCA: B/A&HP: Hall of Records,  
Dover. (Mrs. Robert Kennedy, Sr.,

Description: Lewes, DE)

View of chimney breast paneling, located  
in preacher's room.

Photograph Number: K-171 (#4) 87

NOV 29 1977



83

AUG 24 1978

Name: GOLDEN MINE ~~FARM~~

Location: Near Milford, <sup>Kent County</sup> Delaware

Photographer: James Kimmey

Date: 1969

Location of Negative: DHCA: B/A&HP: Hall of Records, Dover.  
(Mrs. Robert Kennedy, Sr., Lewes, DE)

Description: View of fireplace in dining room.

Photograph Number: K-171 (#5) 7

NOV 29 1977



AUG 24 1978

Name: GOLDEN MINE ~~FARM~~

Location: Near Milford, DE

Photographer: Jean Athan

Date: 10-77

Location of Negative: DHCA: B/A&HP: Hall of Records, Dover.

Description: View of wall paneling of the living room.

*Kent County*

Photograph Number: K-171 (#6) <sup>87</sup>

NOV 29 1977



AUG 24 1978

Name: GOLDEN MINE ~~FARM~~

Location: <sup>Kent County</sup>  
Near Milford, DE

Photographer: Jean Athan

Date:

Location of Negative: <sup>10-77</sup> DHCA:B/A&HP: Hall of Records, Dover.

Description: View of the butterfly cupboard to the  
left of the living room fireplace.

Photograph Number: K-171 (#7) 87

NOV 29 1977