

INDIVIDUAL DATA SHEET

Property Name Stack Barn Property Owner Jerry Haskins
Location Hwy. 94 Spur, vic. Monte Ne Address Route 1, Box 755
Construction Date 1901 Survey No. 0941 Rogers, AR

DESCRIPTION

The Stack Barn is an unusual amalgam of features typical in barn types in Pennsylvania and in the south central states. Its gable roof is sheathed with sheets of tin and features a hay hood with triangular sideboards. A small wooden plaque dated 1901 is displayed in the gabled hood. A large metal vent, centrally fixed, is a later addition to the roof ridge.

The barn plan resembles the midwestern three-portal barn, which was the standard farm structure in the south central United States in the late nineteenth and early twentieth centuries. An expanded version of the transverse crib plan, feed cribs and open stalls flank a central drive or hallway which is closed on the rear elevation. The plan is expanded by adding enclosed side drives. Double sliding doors close the drive and single sliding doors close the side portals on the front elevation, which faces northeast. Three top-hinged doors, designed for ventilation or forking hay or feed, open in the southeast elevation, while two similar doors open on each of the northwest and southwest elevations. The southeast, or rear, elevation, which rises to approximately six feet in height on the continuous footing of native stone, resembles the German bank barn, common in Pennsylvania and the northeast and middle states. Because of the raised rear elevation, the barn

STATEMENT OF SIGNIFICANCE

Criterion: CArea of significance: Architecture

Constructed in 1901, the Stack Barn is a well-preserved example of the gable-roofed Arkansas livestock barn. Designed to shelter stock and feed, the barn is typical of larger multi-function farm structures which were originally common on Arkansas farms. Its steeply pitched roof, which rises to a narrow peak, and partly enclosed hay hood reflect the pre-mechanical era of agriculture, in which unbaled hay was loaded outside the barn and stored loose in its confined loft. The gable barn roof gradually gave way to a more spacious gambrel roof as mechanical balers were perfected. Two different barn types, both of which were unusual in Arkansas farm structures were incorporated in the Stack Barn. The raised rear elevation resembles the German bank barn of the northeast, while the three aisles, which permitted easy access to the stalls, suggest the midwestern three-portal barn, the favored plan for farm construction in the south central states.

Acreage less than 1 acreVerbal Boundary Description From the divergence of Arkansas State Highway #94 and (cont)Quadrangle Name Rogers, Ark. Quadrangle Scale 1:24000UTM Reference: Zone 15 Easting 405780 Northing 4016855

INDIVIDUAL DATA SHEET

Property Name Stack Barn Property Owner _____
Location _____ Address _____
Construction Date _____ Survey No. -0941 _____

DESCRIPTION Continued

was necessarily floored, an unusual feature in Arkansas where earth floors were the rule. Board and batten siding covers the barn. Continuous concrete footings, which probably housed additional side sheds or drives, flank the two side elevations.

STATEMENT OF SIGNIFICANCE

Criterion: _____ Area of significance: _____

VERBAL BOUNDARY CONTINUED

spur #94, proceed east on Highway #94 1.5 miles, then proceed south west down the driveway 530 feet to the southeast corner of the property and the point of beginning. Thence proceed west 100 feet, thence proceed north 100 feet, thence proceed east 100 feet, and thence proceed south 100 feet to the point of beginning.

Acreage _____

Verbal Boundary Description _____

Quadrangle Name _____ Quadrangle Scale _____

UTM Reference: Zone _____ Easting _____ Northing _____

12/14/87

United States Department of the Interior
National Park ServiceNational Register of Historic Places
Continuation Sheet

Section number _____ Page _____

Multiple Resource Area
Thematic GroupName Benton County MRA
State Benton County, ARKANSAS

Nomination/Type of Review

Date/Signature

- | | | | |
|-------------------------------------|-------------------------------------|--|--------------|
| 91. Stack Barn | Entered in the
National Register | for Keeper <u>Melona Byers</u> 1/28/88 | Attest _____ |
| 92. Stockton Building | Entered in the
National Register | for Keeper <u>Melona Byers</u> 1/28/88 | Attest _____ |
| 93. Stroud House | Entered in the
National Register | for Keeper <u>Melona Byers</u> 1/28/88 | Attest _____ |
| 94. Sutherlin Cabin | Entered in the
National Register | for Keeper <u>Melona Byers</u> 1/28/88 | Attest _____ |
| 95. Thurmond House | Entered in the
National Register | for Keeper <u>Melona Byers</u> 1/28/88 | Attest _____ |
| 96. Vinson House | Entered in the
National Register | for Keeper <u>Melona Byers</u> 1/28/88 | Attest _____ |
| 97. Walnut Street Historic District | Entered in the
National Register | for Keeper <u>Melona Byers</u> 1/28/88 | Attest _____ |
| 98. Wasson House | Entered in the
National Register | for Keeper <u>Melona Byers</u> 1/28/88 | Attest _____ |
| 99. Wonderland Cave | Entered in the
National Register | for Keeper <u>Melona Byers</u> 1/28/88 | Attest _____ |
| 100. Young, Col., House | Entered in the
National Register | for Keeper <u>Melona Byers</u> 1/28/88 | Attest _____ |

87002353

NATIONAL REGISTER OF HISTORIC PLACES
EVALUATION/RETURN SHEET

Stack Barn (Benton County MRA)
Benton County
ARKANSAS

DEC 14 1987

Working No. _____

Fed. Reg. Date: 2/7/89

Date Due: 1/14/88 - 1/28/88

Action: ☒ ACCEPT 1-28-88

☐ RETURN

☐ REJECT

Federal Agency: _____

- ☐ resubmission
☐ nomination by person or local government
☐ owner objection
☐ appeal

Entered in the
National Register

Substantive Review: ☐ sample ☐ request ☐ appeal ☐ NR decision

Reviewer's comments:

Recom./Criteria _____

Reviewer _____

Discipline _____

Date _____

_____ see continuation sheet

Nomination returned for: _____ technical corrections cited below
_____ substantive reasons discussed below

1. Name

2. Location

3. Classification

Category	Ownership	Status	Present Use
	Public Acquisition	Accessible	

4. Owner of Property

5. Location of Legal Description

6. Representation in Existing Surveys

Has this property been determined eligible? ☐ yes ☐ no

7. Description

Condition

- ☐ excellent
☐ good
☐ fair

- ☐ deteriorated
☐ ruins
☐ unexposed

Check one

- ☐ unaltered
☐ altered

Check one

- ☐ original site
☐ moved date _____

Describe the present and original (if known) physical appearance

- ☐ summary paragraph
☐ completeness
☐ clarity
☐ alterations/integrity
☐ dates
☐ boundary selection

8. Significance

Period _____ Areas of Significance—Check and justify below

Specific dates _____

Builder/Architect _____

Statement of Significance (*in one paragraph*)

- ☐ summary paragraph
- ☐ completeness
- ☐ clarity
- ☐ applicable criteria
- ☐ justification of areas checked
- ☐ relating significance to the resource
- ☐ context
- ☐ relationship of integrity to significance
- ☐ justification of exception
- ☐ other

9. Major Bibliographical References

10. Geographical Data

Acreage of nominated property _____

Quadrangle name _____

UTM References _____

Verbal boundary description and justification _____

11. Form Prepared By

12. State Historic Preservation Officer Certification

The evaluated significance of this property within the state is:

_____ national _____ state _____ local

State Historic Preservation Officer signature

title _____ date _____

13. Other

- ☐ Maps
- ☐ Photographs
- ☐ Other

Questions concerning this nomination may be directed to _____

Signed _____ Date _____ Phone: _____

Comments for any item may be continued on an attached sheet



No. 39

No. 39

~~Haskins~~ Dur-Stack Barn - 0941D
Vic. Monte Ne
Benton County MRA

Photographed by Benton County Survey Staff-1984

Negatives on file at AHPP

Please refer to the map in the
Multiple Property Cover Sheet
for this property

Multiple Property Cover Sheet Reference Number: 64000022