



#1. Inn, Johnny Seesaw's Historic District  
Peru, Bennington County, Vermont

Photographed by Paula Chadis

Spring 2006

Negative filed at Vermont Division for Historic Preservation

View looking north: Southeast front elevation and southwest side elevation

Photograph #1



#1. Inn, Johnny Seesaw's Historic District

Peru, Bennington County, Vermont


Photographed by Paula Chadis

Spring 2006

Negative filed at Vermont Division for Historic Preservation

View looking south: Northeast side elevation and northwest rear elevation

Photograph #2



#1. Inn, Johnny Seesaw's Historic District

Peru, Bennington County, Vermont

Photographed by Paula Chadis

Spring 2006

Negative filed at Vermont Division for Historic Preservation

View looking east: Northwest rear elevation and Southwest side elevation

Photograph #3



# 1. Inn Interior: 1952 Dining Room Expansion with c. 1938 Furniture

Johnny Seesaw's Historic District

Peru, Bennington County, Vermont

Photographed by Paula Chadis

Spring 2006

Negative filed at Vermont Division for Historic Preservation

View looking South

Photograph # 4





#1. Inn, Circular Fire Pit in main room, Johnny Seesaw's Historic District

Peru, Bennington County, Vermont

Photographed by Paula Chadis

Spring 2006

Negative filed at Vermont Division for Historic Preservation

View looking northwest  
photograph # 5



# 1. Inn Interior: First Floor Landing Log Detail

Johnny Seesaw's Historic District

Peru, Bennington County, Vermont

Photographed by Paula Chadis

Spring 2006

Negative filed at Vermont Division for Historic Preservation

View looking west

Photograph # 6



#1. Inn Interior: Second Floor Guest Room and Hallway

Johnny Seesaw's Historic District

Peru, Bennington County, Vermont

Photographed by Paula Chadik

Spring 2006

Negative filed at Vermont Division for Historic Preservation

View looking west

photograph #7



#1. Inn, Johnny Seesaw's Historic District

Peru, Bennington County, Vermont

Photographed by Mary Parrish

1938 Pre-Conversion Image

CD Filed at Vermont Division for Historic Preservation

View looking West

Southeast front elevation

Photograph #8





#1. Inn, Johnny Seesaw's Historic District

Peru, Bennington County, Vermont

Photographed by Mary Parrish

1938 Pre-Conversion Image

CD filed at Vermont Division for Historic Preservation

View looking South; Northeast side elevation and northwest rear elevation  
photograph #9



#1. Inn Interior: First Floor main room with Innkeepers, William & Mary Parrish (unknown children)

Johnny Seesaw's Historic District

Peru, Bennington County, Vermont

Unknown Photographer

c. 1965 Postcard Image

CD filed at Vermont Division for Historic Preservation

View looking north

photograph # 10



#2. Barn Cottage, Johnny Seesaw's Historic District

Peru, Bennington County, Vermont

Photographed by Paula Chadis

Spring 2006

Negative filed at Vermont Division for Historic Preservation

View looking west: Southeast front elevation and northeast side elevation

Photograph # 11



#3. Chicken House Cottage, Johnny Seesaw's Historic District

Peru, Bennington County, Vermont

Photographed by Paula Chadis

Spring 2006

Negative filed at Vermont Division for Historic Preservation

View looking west: Southeast front elevation and northeast side elevation

Photograph #12





# 4. Courthouse Cottage (background) and #5. Butterfly Cottage (foreground)

Johnny Seesaw's Historic District

Peru, Bennington County, Vermont

Photographed by Paula Chadis

Spring 2006

Negative filed at Vermont Division for Historic Preservation

View looking west: Southwest front elevations and northeast side elevations

Photograph # 13



#6. Garage, Johnny Seesaw's Historic District

Peru, Bennington County, Vermont

Photographed by Paula Chadis

Spring 2006

Negative filed at Vermont Division for Historic Preservation

View looking north: Southeast front elevation and Southwest side elevation

Photograph # 14



#7. Tennis Court, (1 Inn: Southwest elevation in background), Johnny Seesaw's Historic District

Pera, Bennington County, Vermont

Photographed by Paula Chadis

Spring 2006

Negative filed at Vermont Division for Historic Preservation

View looking northeast

Photograph #15



#8. Swimming Pool, (#7 Tennis Court in background) Johnny Seesaw's Historic District

Peru, Bennington County, Vermont

Photographed by Paula Chadis

Spring 2006

Negative filed at Vermont Division for Historic Preservation

View looking south

Photograph #16





#9. Log Cabin, Johnny Seesaw's Historic District

Peru, Bennington County, Vermont


Photographed by Paula Chadis

Spring 2006

Negative filed at Vermont Division for Historic Preservation

View looking South: Northwest rear elevation and northeast side elevation

Photograph #17



#10. Innkeeper's Residence, Johnny Seesaw's Historic District

Peru, Bennington County, Vermont

Photographed by Paula Chadis

Spring 2006

Negative filed at Vermont Division for Historic Preservation

View looking West: Northeast Front elevation and Southeast side elevation

Photograph #18



# 11. Horse Barn, Johnny Seesaw's Historic District

Peru, Bennington County, Vermont

Photographed by Paula Chadis

Spring 2006

Negative filed at Vermont Division for Historic Preservation

View looking northwest: Southeast front elevation

Photograph # 19