



Jacobberger, Josef  
House (1907)

HISTORIC VIEWS SERIES A  
1 OF 2

1502 SW Upper Hall

Portland, Multnomah County, Oregon

Photo Taken  
c. 1907

This photoprint is issued for reference use only. It is not to be copied for resale. Permission for use in a publication, film or video production must be requested in writing from the Photographs Librarian.

Joseph Jacobberger  
residence

Photographs Department  
Oregon Historical Society  
1230 SW Park Avenue  
Portland, Oregon 97205

1502 SW  
Upper Hall

NEGATIVE NUMBER 83676

Lot 117  
Box 2  
p. 15



Jacob Meyer, Josef

HISTORIC VIEWS SERIES A  
2 OF 2

House (1907)

1502 S.W. Upper

Hall,

Portland, Multnomah

County, Oregon

This photoprint is issued for reference use only. It is not to be copied for resale. Permission for use in a publication, film or video production must be requested in writing from the Photographs Librarian.

Photographs Department  
Oregon Historical Society  
1230 SW Park Avenue  
Portland, Oregon 97205

NEGATIVE NUMBER OH 83676

Photo Taken c. 1907

Detail

Jacob Jacob Meyer Residence  
1502 SW Upper Hall Rd.



S

Jacobberger, Josef

House (1907)

1502 S.W. Upper Hall Street,

Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)

3253 S.E. Belmont,

Portland, Oregon 97214

Number 1 of 29.

North (front) elevation.



Jacobberger, Josef

House (1907)

1502 S.W. Upper Hall Street,

Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)

3253 S.E. Belmont,

Portland, Oregon 97214

Number 2 of 29.

North (front) elevation.



Jacobberger, Josef  
House (1907)  
1502 S.W. Upper Hall Street,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 3 of 29.

North (front) elevation, showing details of the bays,  
and of the brackets under the overhangs.



Jacobberger, Josef  
House (1907)  
1502 S.W. Upper Hall Street,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 4 of 29.

North (front) elevation, the entry porch looking east,  
showing original cladding on the end wall and ceiling,  
and the newer siding on the main wall.



Jacobberger, Josef  
House (1907)  
1502 S.W. Upper Hall Street,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 5 of 29.

North (front) and west elevations, showing the  
northwest corner, placement of the west entrance, and  
the first floor stained glass window.



Jacobberger, Josef  
House (1907)  
1502 S.W. Upper Hall Street,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 6 of 29.

West elevation, showing the stained glass window in the  
dining room wall.




Jacobberger, Josef  
House (1907)  
1502 S.W. Upper Hall Street,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 7 of 29.

West elevation, showing details of the concrete  
foundation wall impressed to match the cement-asbestos  
shingles.



Jacobberger, Josef  
House (1907)  
1502 S.W. Upper Hall Street,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 8 of 29.

South (rear) elevation, from the southeast corner,  
showing porch opening and details of shingles. The  
fire escape ramp is visible in the background.



Jacobberger, Josef  
House (1907)  
1502 S.W. Upper Hall Street,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 9 of 29.  
East elevation, with the corner of the north (front)  
elevation.



Jacobberger, Josef  
House (1907)  
1502 S.W. Upper Hall Street,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 10 of 29.

Living room, looking west through the entry hall into the original dining room, now the kitchen, and showing details of the stained glass doors on the shelves flanking the living room entrance.



Jacobberger, Josef  
House (1907)  
1502 S.W. Upper Hall Street,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 11 of 29.

Entrance hall, looking north, showing details of one of the stained glass windows flanking the main entrance, and a detail of the door.



Jacobberger, Josef  
House (1907)  
1502 S.W. Upper Hall Street,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 12 of 29.

Living room, looking east, showing details of the  
window seat and the ceiling.



Jacobberger, Josef  
House (1907)  
1502 S.W. Upper Hall Street,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 13 of 29.

Living room, looking southeast, showing the fireplace,  
bookcases with stained glass doors, stained glass  
window, French doors, and ceiling.



Jacobberger, Josef  
House (1907)  
1502 S.W. Upper Hall Street,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 14 of 29.

Living room, looking southwest, showing stained glass window flanking fireplace, and the top of the built-in bookcase and its stained glass.



Jacobberger, Josef  
House (1907)  
1502 S.W. Upper Hall Street,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 15 of 29.  
Original dining room, now the kitchen, looking west,  
showing the front windows, and the false ceiling. The  
inspection hole opening to the original ceiling is  
visible in the upper-left corner of the photo.



Jacobberger, Josef  
House (1907)  
1502 S.W. Upper Hall Street,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 16 of 29.

Original dining room, now the kitchen, looking west and showing the cabinet doors now holding the stained glass windows that originally protected the built-in cases flanking the entrance of the room.



Jacobberger, Josef  
House (1907)  
1502 S.W. Upper Hall Street,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 17 of 29.

Original dining room, now the kitchen, looking south,  
and showing a detail of the oak floor, and the built-in  
case flanking the entrance.



Jacobberger, Josef  
House (1907)  
1502 S.W. Upper Hall Street,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 18 of 29.

Original dining room, now the kitchen, looking west,  
showing details of the cross timbers of the original  
dining room ceiling, and the supports of the false  
ceiling now in place.



Jacobberger, Josef  
House (1907)  
1502 S.W. Upper Hall Street,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 19 of 29.

Original kitchen, looking northeast and showing the framing of the door into the dining room.




Jacobberger, Josef  
House (1907)  
1502 S.W. Upper Hall Street,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 20 of 29.

Second floor hallway and main staircase, looking east  
down the stairs, and showing the opening into the  
living room and the curving balustrade.



Jacobberger, Josef

House (1907)

1502 S.W. Upper Hall Street,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)

3253 S.E. Belmont,  
Portland, Oregon 97214

Number 21 of 29.

Second floor hallway and landing, looking west, showing  
the built-in cabinets and drawers of the linen closet.




Jacobberger, Josef  
House (1907)  
1502 S.W. Upper Hall Street,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 22 of 29.

Main hallway of the second floor, looking east into the master bedroom, and showing the main balustrade in the hallway and rising to the third floor.



Jacobberger, Josef  
House (1907)  
1502 S.W. Upper Hall Street,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon '97214

Number 23 of 29.  
Second floor bedroom in the northwest corner, looking  
northwest.



Jacobberger, Josef  
House (1907)  
1502 S.W. Upper Hall Street,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 24 of 29.

Central bedroom on the second floor, looking north, and showing the window seat, with the panorama of Portland beyond.



Jacobberger, Josef  
House (1907)  
1502 S.W. Upper Hall Street,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 25 of 29.

Master bedroom, looking northeast, showing the views of  
Portland from the windows.



Jacobberger, Josef  
House (1907)  
1502 S.W. Upper Hall Street,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 26 of 29.

Second floor sitting room, looking southeast, showing  
the fireplace, and the French doors opening to the  
balcony.




Jacobberger, Josef  
House (1907)  
1502 S.W. Upper Hall Street,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 27 of 29.

Third floor landing, showing the door to the solarium,  
and the triangular window over the door.



Jacobberger, Josef

House (1907)

1502 S.W. Upper Hall Street,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)

3253 S.E. Belmont,  
Portland, Oregon '97214

Number 28 of 29.

Large third floor room set under the front gables,  
looking east, and showing the ceiling slanting with the  
east gable.



Jacobberger, Josef  
House (1907)  
1502 S.W. Upper Hall Street,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 29 of 29.  
Wrought iron fence bordering the north lawn.