



Morris Brown House
317 Rochambeau Avenue
Providence, Rhode Island

Photographer: Nancy Sherren

Date: April 1991

Negative: Rhode Island Historical Preservation Commission
150 Benefit Street
Providence, Rhode Island

View: North and west sides of House
from Rochambeau Avenue, facing southeasterly.

Photo #1





Morris Brown House
317 Rochambeau Avenue
Providence, Rhode Island

Photographer: Michael Hebert

Date: April 1991

Negative: Rhode Island Historical
Preservation Commission
150 Benefit Street
Providence, Rhode Island

View: Interior photograph facing north,
from hall.

View: View of the south hall facing north,
showing the staircase.

Photo #3.



Morris Brown House
317 Rochambeau Avenue
Providence, Rhode Island

Photographer: Michael Hebert

Date: April 1991

Negative: Rhode Island Historical Preservation Commission
150 Benefit Street
Providence, Rhode Island

View: North, northeast parlor.

Detail view in the parlor (northwest room, main floor) facing
southeast, showing fireplace mantel and corner post.

Photo #4