

U.S. DEPT.
OF
AGRICULTURE
FOREST SERVICE
**TILLIER
RANGER
STATION**
UMPQUA
NATIONAL FOREST

- 1) Name of Property: Tiller Ranger Station, Station Sign
- 2) City and State: Tiller, OR
- 3) Photographer: Vance Carlson
- 4) Date: 6/85
- 5) Negative Location: USDA Forest Service, Regional Office, Recreation Unit, CRM files.
- 6) Description: Looking southwesterly, view of Depression-era station sign
- 7) Photograph Number: 15-02-TRS-S



- 1) Name of Property: Tiller Ranger Station,
Automotive Shop #26195/22035
- 2) City and State: Tiller, OR
- 3) Photographer: Vance Carlson
- 4) Date: 6/85
- 5) Negative Location: USDA Forest Service, Regional
Office, Recreation Unit, CRM files.
- 6) Description: Looking southwest, view of north and
east elevations of automotive shop
- 7) Photograph Number: 15-02-26195/22035



- 1) Name of Property: Tiller Ranger Station, Barn #2400
- 2) City and State: Tiller, OR
- 3) Photographer: Vance Carlson
- 4) Date: 6/85
- 5) Negative Location: USDA Forest Service, Regional Office, Recreation Unit, CRM files.
- 6) Description: Looking west, view of east elevation of barn
- 7) Photograph Number: 15-02-2400-2



- 1) Name of Property: Tiller Ranger Station,
Residence #1053
- 2) City and State: Tiller, OR
- 3) Photographer: Vance Carlson
- 4) Date: 6/85
- 5) Negative Location: USDA Forest Service, Regional
Office, Recreation Unit, CRM files.
- 6) Description: Looking east, view of main west-
facing facade of crewhouse
- 7) Photograph Number: 15-02-1053



- 1) Name of Property: Tiller Ranger Station,
Residence #1508
- 2) City and State: Tiller, OR
- 3) Photographer: Vance Carlson
- 4) Date: 6/85
- 5) Negative Location: USDA Forest Service, Regional
Office, Recreation Unit, CRM files.
- 6) Description: Looking southeasterly, view of main
north-facing facade and west elevation of
4-vehicle garage
- 7) Photograph Number: 15-02-1508



- 1) Name of Property: Tiller Ranger Station,
Residence #1052
- 2) City and State: Tiller, OR
- 3) Photographer: Vance Carlson
- 4) Date: 6/85
- 5) Negative Location: USDA Forest Service, Regional
Office, Recreation Unit, CRM files.
- 6) Description: Looking northwesterly, view of south
elevation, main east-facing facade and attached
garage of dwelling
- 7) Photograph Number: 15-02-1052



- 1) Name of Property: Tiller Ranger Station,
Residence #1054
- 2) City and State: Tiller, OR
- 3) Photographer: Vance Carlson
- 4) Date: 6/85
- 5) Negative Location: USDA Forest Service, Regional
Office, Recreation Unit, CRM files.
- 6) Description: Looking southeasterly view of west
elevation and main entry of dwelling
- 7) Photograph Number: 15-02-1054-2



- 1) Name of Property: Tiller Ranger Station,
Residence #1054
- 2) City and State: Tiller, OR
- 3) Photographer: Vance Carlson
- 4) Date: 6/85
- 5) Negative Location: USDA Forest Service, Regional
Office, Recreation Unit, CRM files.
- 6) Description: Looking south, view of north-facing
facade of dwelling
- 7) Photograph Number: 15-02-1054-1



- 1) Name of Property: Tiller Ranger Station,
Residence #1056
- 2) City and State: Tiller, OR
- 3) Photographer: Vance Carlson
- 4) Date: 6/85
- 5) Negative Location: USDA Forest Service, Regional
Office, Recreation Unit, CRM files.
- 6) Description: Looking southeasterly, view of
north-facing rear elevation and west elevation
- 7) Photograph Number: 15-02-1056-2



- 1) Name of Property: Tiller Ranger Station, Barn
#2400
- 2) City and State: Tiller, OR
- 3) Photographer: Vance Carlson
- 4) Date: 6/85
- 5) Negative Location: USDA Forest Service, Regional
Office, Recreation Unit, CRM files.
- 6) Description: Looking north, view of south-facing
facade of barn
- 7) Photograph Number: 15-02-2400-1



- 1) Name of Property: Tiller Ranger Station, Garage #1507
- 2) City and State: Tiller, OR
- 3) Photographer: Vance Carlson
- 4) Date: 6/85
- 5) Negative Location: USDA Forest Service, Regional Office, Recreation Unit, CRM files.
- 6) Description: Looking northwest, view of main south-facing facade and east elevation
- 7) Photograph Number: 15-02-1507



- 1) Name of Property: Tiller Ranger Station,
Residence #1058-Detail
- 2) City and State: Tiller, OR
- 3) Photographer: J. Hunt
- 4) Date: 8/84
- 5) Negative Location: USDA Forest Service, Regional
Office, Recreation Unit, CRM files.
- 6) Description: Looking northwesterly, view of east
elevation of dwelling
- 7) Photograph Number: 15-02-1058-2



- 1) Name of Property: Tiller Ranger Station,
Residence #1058
- 2) City and State: Tiller, OR
- 3) Photographer: J. Hunt
- 4) Date: 8/84
- 5) Negative Location: USDA Forest Service, Regional
Office, Recreation Unit, CRM files.
- 6) Description: Looking northeasterly, view of main
south-facing facade and west elevation of dwelling
- 7) Photograph Number: 15-02-1058-1



- 1) Name of Property: Tiller Ranger Station,
Residence #1056
- 2) City and State: Tiller, OR
- 3) Photographer: J. Hunt
- 4) Date: 8/84
- 5) Negative Location: USDA Forest Service, Regional
Office, Recreation Unit, CRM files.
- 6) Description: Looking north, view of main south-
facing facade of dwelling. Note tree cut-outs in
design exclusive to Umpqua National Forest
- 7) Photograph Number: 15-02-1056-1



- 1) Name of Property: Tiller Ranger Station,
Warehouse #2618
- 2) City and State: Tiller, OR
- 3) Photographer: Vance Carlson
- 4) Date: 6/85
- 5) Negative Location: USDA Forest Service, Regional
Office, Recreation Unit, CRM files.
- 6) Description: Looking southeasterly, view of north
elevation and main west-facing facade of warehouse
- 7) Photograph Number: 15-02-2618