



JAN 8 1979

Moss Side

Woodford County, Kentucky

Gloria Mills

Kentucky Heritage Commission

Frankfort, Kentucky

August 1978

NOV 20 1978

Photo 1

Facade of Moss Side taken from
southeast.



Moss Side

Woodford County, Kentucky

Gloria Mills

Kentucky Heritage Commission

Frankfort, Kentucky

August 1978

Photo 2

JAN 8

NOV 20 1978

1979

View of Moss Side taken from north-east showing stone kitchen (at right).



Moss Side

JAN 8 1979

Woodford County, Kentucky

Gloria Mills

Kentucky Heritage Commission

Frankfort, Kentucky

August 1978

NOV 20 1978

Photo 3

View of rear of Moss Side taken
from northwest showing later porch



JAN 8 1979

Moss Side

Woodford County, Kentucky

Gloria Mills

Kentucky Heritage Commission

Frankfort, Kentucky

August 1978

Photo 4

Interior showing original cornice
molding, chair rail, baseboard

and mantle.

NOV 20 1978



Moss Side

NOV 20 1978

Woodford County, Kentucky

Gloria Mills

Kentucky Heritage Commission
Frankfort, Kentucky

August 1978

JAN 8 1979

Photo 5

Interior showing reeded door,
jamb and concentric circle corner
blocks.



Moss Side

Woodford County, Kentucky

Gloria Mills

Kentucky Heritage Commission
Frankfort, Kentucky

August 1978

JAN 8 1979

Photo 6

Interior view showing segmental
arch opening of kitchen fireplace.

NOV 20 1978



Moss Side

Woodford County

Kentucky

Gloria Mills

Kentucky Heritage Commission
Frankfort, Kentucky

August 1978

Photo 7

JAN 8 1979

View of weatherboarded log
structure south of main house

and facing eastward.

NOV 20 1978