

Photographer: James R. Lockhart Negative Filed: Georgia Department of Natural Resources Date: April, 1985 Description (1 of 9); South and West facades; photographer facing northeast.



Photographer: James R. Lockhart Negative Filed: Georgia Department of Natural Resources Date: April, 1985 Description: (2 of 9): South entrance facade; photographer facing northwest.



Photographer: James R. Lockhart Negative Filed: Georgia Department of Natural Resources Date: April, 1985 Description (3 of 9): South entrance facade and steeple; photographer facing northwest.

and a second

III BRAMES

Photographer: James R. Lockhart Negative Filed: Georgia Department of Natural Resources Date: April, 1985 Description (4 of 9): West facade and addition; photographer facing northwest.



Photographer: James R. Lockhart Negative Filed: Georgia Department of Natural Resources Date: April, 1985 Description (5 of 9); North facade with rear additions; photographer facing southeast.



Photographer: James R. Lockhart Negative Filed: Georgia Department of Natural Resources Date: April, 1985 Description (6 of 9): Sanctuary; photographer facing north.



Photographer: James R. Lockhart Negative Filed: Georgia Department of Natural Resources Date: April, 1985 Description (7 of 9): Sanctuary; photographer facing west.



Photographer: James R. Lockhart Negative Filed: Georgia Department of Natural Resources Date: April, 1985 Description (8 of 9): Sanctuary ceiling and roof supports; photographer facing northwest.



Photographer: James R. Lockhart Negative Filed: Georgia Department of Natural Resources Date: April, 1985 Description (9 of 9): Church office addition: photographer facing northeast.

٨