

Dodd Homestead

Location: Near Rehoboth Beach, Sussex County, DE


Photographer: Richard B. Carter Date:

Name:

Location of Negative: Hall of Records, Dover, DE

Description: view of facade and southwest side of farmhouse.

Photograph Number: 1 of 11



Location: Near Rehoboth Beach, Sussex County, Delaware

Photographer: Richard B. Carter Date: 1981

Date: Dec., 1981 Location of Negative: Hall of Records, Dover, DE

Description: View of facade of Dodd House.

2 of 11

Photograph Number:



Locations Near Rehoboth Beach, Sussex County, DE
Photographers Richard B. Carter
Date: Dec., 1981
Location of Negatives Hall of Records, Dover, DE

Description: View of rear of farmhouse and, from left to right, end of carriage house, small shed, wood shed, and poultry house.

Photograph Number: 3 of 11



Location: Near Rehoboth Beach, Sussex County, DE
Photographer: Richard B. Carter
Date: Dec., 1981
Location of Negative: Hall of Records, Dover, DE


Dodd Homestead

Name a

Photograph Number:

Description: Rear view of wood shed, windmill tower, brick root cellar, and northeast side of farmhouse.

4 of 11



Location: Near Rehoboth Beach, Sussex County, Delaware

Photographer: Richard B. Carter Date: Dec., 1981

Location of Negative? Hall of Records, Dover, DE

Description: View of Carriage House and attached shed.

5 of 11

Photograph Numbers



Location: Near Rehoboth Beach, Sussex County, Delaware

Photographer: Richard B. Carter

Date: Dec., 1981

Location of Negative: Hall of Records, Dover, DE

Description: View of Stable from southwest

Photograph Number: 6 of 11



Dodd Homestead

Location: Near Rehoboth Beach, Sussex County, Delaware

Photographer: Richard B. Carter

Date: Dec., 1981

Name:

Location of Negative: Hall of Records, Dover, DE

Description: View of, from left: equipment shed, granary, and corn crib.

Photograph Numbers 7 of 11



Photographer: Rehoboth Beach, Sussex County, Delaware Richard B. Carter Date: Dec., 1981

Location of Negative: Hall of Records, Dover, DE

Description:

View of small barn with attached corn crib.

Photograph Number | 8 of 11



Location: Near Rehoboth Beach, Sussex County, Delaware


Photographer: Richard B. Carter

Date: Dec., 1981

Location of Negative: Hall of Records, Dover, DE

Description: Interior view of small barn showing old farm wagons stored within.

Photograph Numbers 9 of 11



Location: Near Rehoboth Beach, Sussex County, Delaware

Photographer: Richard B. Carter

Date: Dec., 1981

Location of Negative: Hall of Records, Dover, DE

Description: Detail of door on large dairy barn showing iron hardware

Photograph Number: 10 of 11



Location: Near Rehoboth Beach, Sussex County, DE

Photographer: Richard B. Carter Date: Dec., 1981

Location of Negative: Hall of Records, Dover, DE

Description: Interior view of large dairy barn.

ll of ll

Photograph Numbers