


Larry Slie 1985 Negatives: Colorado Historical Society

Photo 1 West wing. Looking northwest




- Larry Slie 1985 Negatives: Colorado Historical Society
- Photo 2 West wing. Looking northwest.



Larry Slie 1985 Negatives: Colorado Historical Society

Photo 3 West wing showing original adobe bricks



Larry Slie 1985 Negatives: Colorado Historical Society

Photo 4 East wing.



Larry Slie 1985 Negatives: Colorado Historical Society


Photo 5 Looking north between east and west wings.



Larry Slie 1985 Negatives: Colorado Historical Society

Photo 6

East wing, looking north.



Larry Slie 1985 Negatives: Colorado Historical Society

Photo 7

Door of east wing.



Larry Slie 1985 Negatives: Colorado Historical Society

Photo 8

Porch on north side of west wing.



Larry Slie 1985 Negatives: Colorado Historical Society

Photo 9

Doorways into M-4 and M-3. These doors are not original but were cut as early as 1870s.



```
Francisco Plaza
LaVeta, Huerfano County, CO
```

```
Larry Slie
```

1985

```
Negatives: Colorado Historical Society
```

Photo 10

North wall of east wing. It appears as it did in 1862. The reinforcements added in

1958 were to prevent the walls from further pulling apart.



- Larry Slie
- 1985
- Negatives: Colorado Historical Society
- Photo 11 Southwest corner of west wing where musuem joins private residence. At left, is doorto

H-1. At right, door to H-2.



Larry Slie 1985 Negatives: Colorado Historical Society

Photo 12

Fireplace in W-7



Larry Slie 1985 Negatives: Colorado Historical Society

Photo 13

Fireplace in M-6



Larry Slie 1985 Negatives: Colorado Historical Society

Photo 14

Fireplace in W-4.



Larry Slie 1985 Negatives: Colorado Historical Society

Photo 15

Looking from W-4 into W-6.





Larry Slie 1985 Negatives: Colorado Historical Society

Photo 16.

Fireplace in W-5.



Larry Slie 1985 Negatives: Colorado Historical Society

Photo 17

Stove in E-1. Fireplace has been covered over and woodstove connected to old chimney.



Larry Slie 1985 Negatives: Colorado Historical Society

Photo 18

Stove in E-4. Chimney, as with E-1, has been closed.